



report date: 2024-03-28

General information

Make	FORD
Model	RANGER 350 H/R P/V
Colour	White
Year of manufacture	2013
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	310 Nm at 1.300 rpm
Engine capacity	2.200 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	39.2 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-03
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-14
MOT pass rate	50 %
MOT passed	5
Failed MOT tests	5
Total advice items	20
Total items failed	8

MOT #10	2024-01-15 11:00
MOT test number	523741013226
Result	✓ Passed
Next expiry date	2025-01-14

MOT #9	2024-01-12 10:44
MOT test number	762739425287
Result	✗ Failed

- Fail

Offside Rear Position lamp has a product on the lens or light source which shows white light to the rear (4.2.3 (b) (ii))
- Fail

Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))

**MOT #8**

2022-11-02 14:59

MOT test number

271489305609

Result

✓ Passed

- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Front Headlamp lens slightly defective both (4.1.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front Brake pedal wearing smooth (1.1.2 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7

2022-10-31 10:26

MOT test number

676203483199

Result

✗ Failed

- Fail** Nearside Rear Electrical wiring insecure and in contact with sharp edges (4.11 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Exhaust emissions exceed default limit of 0.7m-1 (8.2.2.2 (b))
- Minor** Front Headlamp lens slightly defective both (4.1.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake pedal wearing smooth (1.1.2 (c))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #6** 2021-09-23 09:46**MOT test number** 870215767272**Result** ✓ Passed**Minor** Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #5** 2021-09-17 15:37**MOT test number** 219378142577**Result** ✗ Failed**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #4** 2020-09-15 09:41**MOT test number** 709092788976**Result** ✓ Passed**MOT #3** 2020-09-11 08:20**MOT test number** 700756875788**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2019-08-02 07:17**MOT test number** 914193214484**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #1	2019-07-31 14:11
MOT test number	241042517903
Result	✗ Failed
Fail	Nearside Rear Leaf spring fractured (5.3.1 (b) (i))
Advice	Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 January 2025

Tax status	Valid until 1 September
-------------------	-------------------------

Days left	125
------------------	-----

MOT expiry date	14 January 2025
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	GV63 FMA
Plate since	2019-03-28
Current registration	GV63 FMA
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-31
Last registration	2024-01-15
Complete history	See info



Registration #1	2013-12-31	25 mi
Registration #2	2019-07-31	68.528 mi
Registration #3	2019-08-02	68.532 mi
Registration #4	2020-09-11	78.527 mi
Registration #5	2020-09-15	78.529 mi
Registration #6	2020-09-15	78.529 mi
Registration #7	2020-09-15	78.529 mi
Registration #8	2020-09-15	78.529 mi
Registration #9	2020-09-15	78.529 mi
Registration #10	2020-09-15	78.529 mi
Registration #11	2020-09-15	78.529 mi
Registration #12	2020-09-15	78.529 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1974 mm
Height	2590 mm
Length	5680 mm
Kerb weight	1951 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	9
Engine number	60967