



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	AVENSIS VVT-I XT3
Colour	Silver
Year of manufacture	2004
Top speed	109 mph
0 - 60 mph	10.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	37.2 mpg
Consumption combined	30.4 mpg
CO2 emission	224 g/km
CO2 label	K





MOT history

MOT expiry date	2022-03-18
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	32
Total items failed	12

MOT #21	2021-03-19 12:36
MOT test number	826314641791
Result	✓ Passed
Next expiry date	2022-03-18

MOT #20	2020-08-24 15:16
MOT test number	456492523130
Result	✓ Passed

MOT #19	2019-08-23 13:25
MOT test number	187721669997
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #18	2018-08-24 10:48
MOT test number	994910742528
Result	✓ Passed

MOT #17	2018-08-24 09:02
MOT test number	125894500444
Result	✗ Failed
MAJOR	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #16** 2017-08-24 15:04**MOT test number** 463308927558**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Nail in tyre**Advice** Eml light on**Advice** Nearside Rear Nail in tyre**MOT #15** 2016-08-25 13:14**MOT test number** 750472611788**Result** ✓ Passed**Advice** Offside Front Valve stem slightly damaged (4.1.D.1e)**Advice** Engine covers and under trays fitted**MOT #14** 2016-08-25 13:14**MOT test number** 313410998518**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Engine covers and under trays fitted**Advice** Offside Front Valve stem slightly damaged (4.1.D.1e)**MOT #13** 2015-08-10 17:43**MOT test number** 665972525256**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #12** 2015-08-10 16:01**MOT test number** 675832225204**Result** ✗ Failed

- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Nail in nearside front tyre
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Spare wheel under-inflated

MOT #11 2014-08-02 13:06**MOT test number** 178914114291**Result** ✓ Passed**MOT #10** 2014-01-08 14:21**MOT test number** 727068404071**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2012-11-12 13:16**MOT test number** 346647212397**Result** ✓ Passed

- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Both rear brake discs corroded.

**MOT #8** 2012-11-12 13:16**MOT test number** 207787112359**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Both rear brake discs corroded.**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2010-05-11 16:24**MOT test number** 192391230150**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2010-05-05 13:28**MOT test number** 100985220164**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Headlamp excessively damaged so that the light output is severely reduced (1.7.5a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2009-05-08 13:50**MOT test number** 980108029162**Result** ✓ Passed**Advice** Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Notice** Strongly advise cleaning under vehicle**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Rear coil spring worn (2.4.C.1b)**MOT #4** 2008-05-06 15:28**MOT test number** 391207228176**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #3** 2008-05-06 15:28**MOT test number** 550047528118**Result** ✓ Passed**MOT #2** 2007-05-14 14:56**MOT test number** 804344137194**Result** ✓ Passed**MOT #1** 2007-05-11 11:27**MOT test number** 244501737153**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
15 February 2022

✕
MOT

Expired:
18 March 2022

Tax status	Expired at 15 February 2022
Days left	805 days too late
MOT expiry date	18 March 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-05-25
Last registration	2021-03-19
Complete history	See info



Registration #1	2004-05-25	25 mi
Registration #2	2007-05-11	37.142 mi
Registration #3	2007-05-14	37.226 mi
Registration #4	2008-05-06	48.751 mi
Registration #5	2009-05-08	61.880 mi
Registration #6	2010-05-05	71.572 mi
Registration #7	2010-05-11	71.856 mi
Registration #8	2012-11-12	71.918 mi
Registration #9	2014-01-08	79.520 mi
Registration #10	2014-08-02	80.984 mi
Registration #11	2015-05-20	81.377 mi
Registration #12	2016-05-20	81.377 mi
Registration #13	2017-05-20	81.377 mi
Registration #14	2018-05-20	81.377 mi
Registration #15	2019-05-20	81.377 mi
Registration #16	2020-05-20	81.377 mi
Registration #17	2021-03-19	81.377 mi
Registration #18	2021-03-19	81.377 mi
Registration #19	2021-03-19	81.377 mi
Registration #20	2021-03-19	81.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1AZ1358652