



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA CLUB AC
Colour	Silver
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-10-28
Pictures	50
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-26
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-18
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	21
Total items failed	6

MOT #17 2023-09-19 11:03

MOT test number 233734388209

Result ✓ Passed

Next expiry date 2024-09-18

Advice Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #16 2022-08-08 13:43

MOT test number 174122137583

Result ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15 2021-07-09 08:51

MOT test number 521752281108

Result ✓ Passed

Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #14**

2021-07-09 08:51

MOT test number

365291734950

Result

✗ Failed

Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #13**

2020-07-09 14:21

MOT test number

997297331181

Result

✓ Passed

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Nearside Front Lower Steering linkage ball joint has slight play (2.1.3 (b) (i))**MOT #12**

2020-07-09 14:21

MOT test number

367101235640

Result

✗ Failed

Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Nearside Front Lower Steering linkage ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #11**

2019-07-30 09:20

MOT test number

407207443870

Result

✓ Passed

**MOT #10** 2019-07-16 10:58**MOT test number** 523117460328**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2018-07-14 09:09**MOT test number** 151421180922**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MOT #8** 2018-07-11 10:35**MOT test number** 526550082023**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MOT #7** 2017-07-11 11:21**MOT test number** 147134410755**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #6** 2016-08-09 14:56**MOT test number** 802038028663**Result** ✓ Passed



MOT #5	2015-09-10 16:20
MOT test number	512073901251
Result	✓ Passed
MOT #4	2015-03-07 11:18
MOT test number	569256965058
Result	✓ Passed
MOT #3	2014-06-11 10:29
MOT test number	727272864162
Result	✓ Passed
MOT #2	2013-06-12 16:14
MOT test number	726673063176
Result	✓ Passed
MOT #1	2012-10-25 10:37
MOT test number	109139092275
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	EA59HWF
Plate since	2019-06-29
Current registration	EA59HWF
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-10-14
Last registration	2023-09-19
Complete history	See info



Registration #1	2009-10-14	14 mi
Registration #2	2012-10-25	20.192 mi
Registration #3	2013-06-12	21.386 mi
Registration #4	2014-06-11	28.404 mi
Registration #5	2015-03-07	32.586 mi
Registration #6	2015-09-10	32.603 mi
Registration #7	2016-08-09	37.438 mi
Registration #8	2017-07-11	42.331 mi
Registration #9	2018-07-11	49.161 mi
Registration #10	2018-07-14	49.174 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi
Registration #18	2019-05-20	55.277 mi
Registration #19	2019-05-20	55.277 mi
Registration #20	2019-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1095 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1219584