





report date: 2024-03-29

General information

| Make | MERCEDES |
|---------------------|----------------------|
| Model | CLK CLK220 CDI SPORT |
| Colour | Silver |
| Year of manufacture | 2009 |
| Top speed | 137 mph |
| 0 - 60 mph | 10.4 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 148 BHP |
|-------------------------|---------------------|
| Max. torque | 340 Nm at 2.000 rpm |
| Engine capacity | 2.148 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.1 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 43.5 mpg |
| CO2 emission | 183 g/km |
| CO2 label | I |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-03

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

arm (5.3.4 (b) (i))

| MOT expiry date | 2024-08-22 |
|--------------------|------------|
| MOT pass rate | 93 % |
| MOT passed | 13 |
| Failed MOT tests | 1 |
| Total advice items | 13 |
| Total items failed | 3 |

| MOT #14 | 2023-08-23 11:56 |
|------------------|------------------|
| MOT test number | 116300567386 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-22 |

| MOT #13 | 2023-08-16 13:41 | |
|--|---|--|
| MOT test | number 781867479531 | |
| Result | ✓ Passed | |
| Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated Front track control arm (5.3.4 (b) (i)) | | |
| Minor | Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated front track control | |

| MOT #12 | 2023-08-11 12:16 |
|---|--------------------------|
| MOT test number | 620057638825 |
| Result | × Failed |
| Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i)) | |
| Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorate arm (5.3.4 (b) (i)) | ed Front track control |
| Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriora arm (5.3.4 (b) (i)) | ated front track control |

CarCheck.co.uk page 3/12



| MOT #11 | 2022-09-24 09:20 |
|---------|------------------|
| | |

MOT test number 351164394374

MOT #10 2021-09-14 14:03

MOT test number 367526848430

Result

Passed

MOT #9 2020-11-18 11:13

MOT test number 599036396680

Result \(\sqrt{Passed} \)

Advice Front Brake disc worn, pitted or scored, but not seriously weakened BOTH FRONT DISCS (1.1.14 (a) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8 2019-05-17 10:08

MOT test number 544199200060

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #7 2018-05-17 13:47

MOT test number 951752099267

Result ✓ Passed

MOT #6 2017-05-18 09:34

MOT test number 627774388666

Result
✓ Passed

Advice Offside front tyre outer wall has a slight cut but cords not exposed

Advice O/s/n/s rear tyres slightly perished & inner edges slightly worn

Advice Undertrays fitted obscuring underside components

CarCheck.co.uk page 4/12



MOT #5 2016-05-18 08:49

MOT test number 706117512433

MOT #4 2015-05-21 15:01

MOT test number 846401545131

Result \(\sqrt{Passed} \)

Advice Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #3 2014-05-20 10:44

MOT test number 346010144160

Result Passed

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

MOT #2 2013-05-03 09:42

MOT test number 859613723103

Result ✓ Passed

MOT #1 2012-05-17 11:32

MOT test number 256998032444

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 155 |
| MOT expiry date | 22 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | T |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |
| Damage 2 | |
| Date | |



Extra MERCEDES salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> . | |
| | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this MERCEDES had different number plates. | |
| Number of plates | , |
| Current registration | JK UK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #16

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2009-05-21 |
| Last registration | 2023-08-23 |
| Complete history | See info |



| Registration #1 | 2009-05-21 | 13 mi |
|------------------|------------|-----------|
| Registration #2 | 2012-05-17 | 33.130 mi |
| Registration #3 | 2013-05-03 | 37.737 mi |
| Registration #4 | 2014-05-20 | 41.076 mi |
| Registration #5 | 2015-05-21 | 46.102 mi |
| Registration #6 | 2016-05-18 | 49.205 mi |
| Registration #7 | 2017-05-18 | 51.619 mi |
| Registration #8 | 2018-05-17 | 53.826 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.177 es |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.177 es |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| | | |

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Dimensions & weight

| Width | 1991 mm |
|-------------|---------|
| Height | 1415 mm |
| Length | 4652 mm |
| Wheel base | 2715 mm |
| Kerb weight | 1595 kg |

Additional information

| Fuel tank capacity | 68 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 64696630637445 |

CarCheck.co.uk page 12/12