



report date: 2024-03-28

General information

Make	MAZDA
Model	2 TS
Colour	Black
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	121 Nm at 3.500 rpm
Engine capacity	1.349 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	54.3 mpg
CO2 emission	125 g/km
CO2 label	D



**MOT history**

<b>MOT expiry date</b>	2021-05-05
<b>MOT pass rate</b>	64 %
<b>MOT passed</b>	7
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	60
<b>Total items failed</b>	5

<b>MOT #11</b>	2020-05-06 10:30
----------------	------------------

<b>MOT test number</b>	446083892633
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Next expiry date</b>	2021-05-05
-------------------------	------------

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Headlamp lens slightly defective nearside and offside (4.1.1 (b) (i))
- Advice** Gearbox mount rubber bush has splits, oil sump has corrosion, damage on windscreen
- Advice** Nearside and offside inner sill panel has corrosion
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive nearside and offside (5.3.6 (a) (i))
- Advice** Middle exhaust shield loose
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #10**

2020-05-04 12:39

**MOT test number**

642053380841

**Result****✗ Failed**

- Advice** Middle exhaust shield loose
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive nearside and offside (5.3.6 (a) (i))
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Gearbox mount rubber bush has splits, oil sump has corrosion, damage on windscreen
- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Minor** Headlamp lens slightly defective nearside and offside (4.1.1 (b) (i))
- Advice** Nearside and offside inner sill panel has corrosion
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2019-05-13 08:42

**MOT test number**

234364471208

**Result****✓ Passed**

- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Steering rack has slight free play detected at steering wheel (2.3 (a) (i))



MOT #8

2018-04-24 09:05

MOT test number

120560678904

Result		✓ Passed
Advice	Nearside front wishbone bush deteriorated rear bush	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	
Advice	Underbody has corrosion	
Advice	Undertrays and sill covers fitted	
Advice	Nearside and offside inner sill panel has corrosion	
Advice	Nearside and offside rear tyres has a wear on the inner and outer edges also has cracks	
Advice	Offside front wishbone bush deteriorated rear bush	
Advice	Oil leak	
Advice	Oil sump corroded	
Advice	Front registration plate cracked	
Advice	Nearside front tyre has a wear on the inner and outer edges also has cracks	

**MOT #7**

2018-04-23 12:15

**MOT test number**

221410855138

**Result****✗ Failed**

- Advice** Nearside front wishbone bush deteriorated rear bush
- Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Advice** Underbody has corrosion
- Advice** Undertrays and sill covers fitted
- Advice** Nearside and offside inner sill panel has corrosion
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside and offside rear tyres has a wear on the inner and outer edges also has cracks
- Advice** Oil leak
- Advice** Offside front wishbone bush deteriorated rear bush
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Advice** Oil sump corroded
- Advice** Front registration plate cracked
- Advice** Nearside front tyre has a wear on the inner and outer edges also has cracks
- Fail** Offside Obligatory mirror insecure (8.1.1)

**MOT #6**

2017-04-04 14:13

**MOT test number**

506664174506

**Result****✓ Passed**

- Advice** Front registration plate cracked

**MOT #5** 2017-04-04 12:32**MOT test number** 405117163565**Result** ✗ Failed**Advice** Front registration plate cracked**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #4** 2016-04-20 11:42**MOT test number** 740462311875**Result** ✓ Passed**MOT #3** 2014-04-16 10:57**MOT test number** 925686204101**Result** ✓ Passed**Notice** Nearside rear tyre cracking**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Notice** Nail in nearside rear tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Exhaust corroded**Notice** Items removed from driver's view prior to test**Notice** Offside rear tyre cracking



MOT #2	2013-05-07 11:25
MOT test number	937367123111
Result	✓ Passed
Notice	Nail in offside rear tyre
Notice	Items removed from driver's view prior to test

MOT #1	2013-05-07 11:25
MOT test number	685507823105
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)
Notice	Nail in offside rear tyre
Notice	Items removed from driver's view prior to test



Tax & MOT check

X

Untaxed

Tax expired:  
25 January 2021

X

MOT

Expired:  
5 May 2021

Tax status	Expired at 25 January 2021
Days left	1189 days too late
MOT expiry date	5 May 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-11-12
Last registration	2020-05-06
Complete history	<a href="#">See info</a>



Registration #1	2009-11-12	23 mi
Registration #2	2013-05-07	38.578 mi
Registration #3	2014-04-16	47.319 mi
Registration #4	2016-04-20	76.909 mi
Registration #5	2017-04-04	90.097 mi
Registration #6	2017-04-04	90.097 mi
Registration #7	2019-05-06	90.097 mi
Registration #8	2019-05-06	90.097 mi
Registration #9	2019-05-06	90.097 mi
Registration #10	2019-05-06	90.097 mi
Registration #11	2019-05-06	90.097 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ZJ 797478