





report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 230 KOMPRESSOR SPECIAL EDITION
Colour	Silver
Year of manufacture	2004
Top speed	147 mph
0 - 60 mph	7.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	279 Nm at 2.500 rpm
Engine capacity	2.295 сс
Cylinders	4
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	39.8 mpg
Consumption combined	28.8 mpg
CO2 emission	226 g/km
CO2 label	L



CarCheck.co.uk page 1/15



Internet history

F	n	n	2

, _	
Date	2021-07-14
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Lifti y 1	
Date	2021-07-13
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-08-13
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	21
Total items failed	15

MOT #22		2023-08-14 09:05
MOT test	number	786269958466
Result		✓ Passed
Next expi	ry date	2024-08-13
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	O/s/f brake slightly binding	

CarCheck.co.uk page 3/15



Advice

LL53FMP

report date: 2024-03-28

MOT #21 2023-06-28 09:43 519908487056 **MOT** test number Result × Failed Fail Offside Front Service brake excessively binding (1.2.1 (f)) Fail Nearside Front Headlamp aim too low (4.1.2 (a)) Fail Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Advice Offside Rear Brake pipe corroded, covered in grease or other material front to back (1.1.11 (c)) **Advice** Corrosion around battery tray difficult to see all Fail Offside Rear Rear fog lamp not working (4.5.1 (a) (ii)) Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e)) **Advice** Fail Headlamp levelling device inoperative (4.1.5 (a)) **Advice** Oil leak, but not excessive Gearbox (8.4.1 (a) (i)) Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Fail

MOT #20	2021-09-16 11:28
MOT test number	778666613352
Result	✓ Passed

Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

CarCheck.co.uk page 4/15



report date: 2024-03-28

✓ Passed

MOT #19 2021-09-07 10:17

MOT test number 266504475157

Result X Failed

Fail Offside Rear Direction indicator light intensity significantly reduced (4.4.3 (a))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Steering box has excessive free play detected at the steering wheel to the extent that safe steering is affected (steering box fitted) (2.3 (a) (ii))

Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))

Fail Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #18 2020-07-01 09:52

MOT test number 107992034537

Result

Passed

Advice Lift in bottom swivels

Result

MOT #17 2019-05-17 10:45

MOT test number 414984536741

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #16 2018-05-02 15:02

MOT test number 455455439200

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #15 2018-05-02 08:26

MOT test number 231278620588

Result X Failed

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Fail Offside Rear Rear fog lamp not working (1.3.2b)

MOT #14 2017-05-19 10:12

MOT test number 823982229502

Result ✓ Passed

MOT #13 2016-05-16 11:52

MOT test number 650481044990

Result \rightarrow Passed

MOT #12 2015-05-18 16:57

MOT test number 158188135107

Result
✓ Passed

Notice All tyres age-ing (10 years old)

Advice Offside Front Front wheel bearing has slight play (2.5.A.3c)

MOT #11 2015-05-16 10:20

MOT test number 735516535132

Result X Failed

Advice Offside Front Front wheel bearing has slight play (2.5.A.3c)

Fail Offside Front coil spring broken (2.4.C.1a)

Notice All tyres age-ing (10 years old)

CarCheck.co.uk page 6/15



Result

LL53FMP

report date: 2024-03-28

✓ Passed

MOT #10	2014-05-10 10:14
MOT test number	419390734194
Result	✓ Passed
MOT #9	2013-05-23 11:20
MOT test number	976043743122
Result	✓ Passed
MOT #8	2012-11-15 11:16
MOT test number	435920322343
Result	✓ Passed
MOT #7	2011-09-07 14:11
MOT test number	407850051248
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) MOT #6	2010-10-01 08:56
	2010-10-01 08:56 280254770247
MOT #6	
MOT #6 MOT test number	280254770247
MOT #6 MOT test number	280254770247
MOT #6 MOT test number Result	280254770247 ✓ Passed
MOT #6 MOT test number Result MOT #5	280254770247 Passed 2009-09-14 10:45
MOT #6 MOT test number Result MOT #5 MOT test number	280254770247 Passed 2009-09-14 10:45 993847159261
MOT #6 MOT test number Result MOT #5 MOT test number	280254770247 Passed 2009-09-14 10:45 993847159261

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #3

MOT test number

Result

Advice Centre Steering damper slight oil seepage (2.2.C.1f)

 MOT #2
 2007-01-19 08:44

 MOT test number
 580079217032

 Result
 ✓ Passed

 MOT #1
 2007-01-18 15:26

 MOT test number
 412778817052

Result × Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Under trays

CarCheck.co.uk page 8/15



Tax & MOT check



Tax expired: 12 November 2023



Expires: 13 August 2024

Tax status	Expired at 12 November 2023
Days left	168 days too late
MOT expiry date	13 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	

THE PROPERTY OF THE PROPERTY O	
Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-01-23
Last registration	2023-08-14
Complete history	See info



Registration #1	2004-01-23	23 mi
Registration #2	2007-01-18	25.724 mi
Registration #3	2007-01-19	25.724 mi
Registration #4	2007-09-25	27.658 mi
Registration #5	2008-08-26	32.975 mi
Registration #6	2009-09-14	37.440 mi
Registration #7	2010-10-01	38.887 mi
Registration #8	2011-09-07	39.615 mi
Registration #9	2012-11-15	40.346 mi
Registration #10	2013-05-23	40.458 mi
Registration #11	2014-05-10	45.400 mi
Registration #12	2015-05-16	48.830 mi
Registration #13	2015-05-18	48.830 mi
Registration #14		11.777 es
Registration #15		71.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		71.777 es
Registration #22		11.777 es
Registration #23		11.777 esi
Registration #24		71.777 es
Registration #25		11.777 es



			_		
- 11	manc	Innc	λ.	MOL	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	1715 mm
Height	1281 mm
Length	4010 mm
Wheel base	2400 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11198340087137

CarCheck.co.uk page 15/15