



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Black
Year of manufacture	2010
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-08-28
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-08-24
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	34
Total items failed	10

MOT #14	2021-08-25 17:04
MOT test number	950036465613
Result	✓ Passed
Next expiry date	2022-08-24

MOT #13	2020-10-28 08:46
MOT test number	388208627842
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12	2019-10-31 11:28
MOT test number	647706478337
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge bold on inner edge (5.2.3 (e))
Advice	Offside Front Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

MOT #11	2018-11-06 10:02
MOT test number	949965383581
Result	✓ Passed
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #10** 2018-11-04 10:41**MOT test number** 783555761414**Result** ✗ Failed

- Fail** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Fail** Nearside Headlamp levelling device inoperative (4.1.5 (a))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #9 2017-10-27 08:39**MOT test number** 302833291272**Result** ✓ Passed

- Advice** Nearside door damaged
- Advice** Offside front tyre slight perishing
- Advice** Under trays fitted
- Advice** Nearside rear body panel damaged

MOT #8 2016-11-04 15:44**MOT test number** 655712873136**Result** ✓ Passed

- Advice** Nearside Front tyre deteriorating in the tread area
- Advice** Exhaust has a minor leak of exhaust gases front to centre joint (7.1.2)
- Advice** Both outer sill areas slightly damaged
- Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #7**

2016-11-04 10:47

MOT test number

156709164355

Result**✗ Failed****Advice** Exhaust has a minor leak of exhaust gases front to centre joint (7.1.2)**Advice** Nearside Front tyre deteriorating in the tread area**Fail** Front registration plate insecure (6.3.1b)**Advice** Both outer sill areas slightly damaged**Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #6**

2015-10-24 15:26

MOT test number

477366243981

Result**✓ Passed****Advice** Minor damage to o/s/r sill area.**Advice** Front number plate slightly insecure.**Advice** Both front tyres wearing on edges of tread, O/S/F in particular.**MOT #5**

2015-10-24 10:09

MOT test number

573933667474

Result**✗ Failed****Advice** Both front tyres wearing on edges of tread, O/S/F in particular.**Advice** Minor damage to o/s/r sill area.**Fail** Offside Rear fog lamp not working (1.3.2b)**Advice** Front number plate slightly insecure.



MOT #4 2014-11-08 15:33

MOT test number 457932214474

Result ✓ Passed

- Notice** Water inside offside rear lamp
- Notice** Electric headlamp adjuster does not work on nearside headlamp
- Notice** Nearside front wheel slightly buckled

MOT #3 2014-11-01 12:41

MOT test number 256505304301

Result ✗ Failed

- Notice** Electric headlamp adjuster does not work on nearside headlamp
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Notice** Nearside front wheel slightly buckled
- Notice** Water inside offside rear lamp
- Pass with rectification** Nearside Headlamp aim too high (1.8)

MOT #2 2013-11-07 14:33

MOT test number 296801013330

Result ✓ Passed

- Notice** Cut in sidewall on nearside front tyre, deep enough to reach the cords, but below the 25mm length limit
- Notice** Nearside front wheel slightly buckled



MOT #1	2013-11-07 14:33
MOT test number	469611613300
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)
Pass with rectification	Nearside Headlamp aim too low (1.8)
Notice	Nearside front wheel slightly buckled
Notice	Cut in sidewall on nearside front tyre, deep enough to reach the cords, but below the 25mm length limit



Tax & MOT check

×

Untaxed

Tax expired:
15 December 2021

×

MOT

Expired:
24 August 2022

Tax status

Expired at 15 December 2021

Days left

867 days too late

MOT expiry date

24 August 2022

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-30
Last registration	2021-08-25
Complete history	See info



Registration #1	2010-03-30	13 mi
Registration #2	2013-11-07	19.583 mi
Registration #3	2014-11-01	10.159 mi
Registration #4	2014-11-08	10.372 mi
Registration #5	2015-10-24	16.882 mi
Registration #6	2015-10-24	16.882 mi
Registration #7	2016-11-04	19.344 mi
Registration #8	2016-11-04	19.344 mi
Registration #9	2016-11-04	19.344 mi
Registration #10	2016-11-04	19.344 mi
Registration #11	2016-11-04	19.344 mi
Registration #12	2016-11-04	19.344 mi
Registration #13	2016-11-04	19.344 mi
Registration #14	2016-11-04	19.344 mi
Registration #15	2016-11-04	19.344 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 058721