





report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT T220 LR DCB
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-09-20

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-09-19
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	14
Total items failed	7

MOT #16		2023-09-20 12:33
MOT test	number	940007852973
Result		✓ Passed
Next expi	ry date	2024-09-19
Advice	Rear exhaust box poor condition	
Advice	Tyre slightly damaged/cracking or perishing nearside and offside rear pe	erished (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #15	2023-09-20 08:29
MOT test number	364118767779
Result	≍ Failed
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3	3.4 (b) (ii))
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Tyre slightly damaged/cracking or perishing nearside and offside rear peri	shed (5.2.3 (d) (ii))
Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4	(b) (ii))
Advice Rear exhaust box poor condition	
Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, ingress of dirt (6.1.7 (g) (ii))	no longer prevents the
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/13



MOT test number

545585303525

Result

Advice Both wiper blades split on ends

Advice Offside Rear Tyre slightly damaged/cracking or perishing badley perished (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge very close and worn bald on edges (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13		2021-08-04 08:24
MOT test	number	655564285297
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge On edges (5.2.3 (e))	
Advice	Offside rear tyre wall & tread cracking	
Advice	Offside Front Tyre worn close to legal limit/worn on edge On edges (5.2.3 (e))	

MOT #12		2020-06-09 14:24
MOT test number		817585231079
Result		✓ Passed
MOT #11		2020-06-09 14:24
MOT test number		202534587635
Result		X Failed
Pass with rectification	Central Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #10	2019-11-30 09:45
MOT test number	981896667833
Result	✓ Passed

CarCheck.co.uk page 4/13



 MOT #9
 2019-11-30 09:45

 MOT test number
 324263493189

 Result
 X Failed

Pass with rectification

Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

 MOT #8
 2019-04-24 12:55

 MOT test number
 615994464189

 Result
 ✓ Passed

 MOT #7
 2018-04-27 08:35

 MOT test number
 506089597081

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (3.5.1g)

MOT #6	2017-04-21 08:13
MOT test number	520176520288
Result	√ Passed
MOT #5	2016-04-11 14:31
MOT test number	265428222393
Result	√ Passed
MOT #4	2015-05-06 11:12

2015-05-06 11:12
817486125167
✓ Passed

MOT #3	2014-05-03 08:47
MOT test number	559733924155
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #2	2013-05-03 11:56
MOT test number	199103123122
Result	✓ Passed
MOT #1	2012-04-26 11:47
MOT #1 MOT test number	2012-04-26 11:47 316907912192

CarCheck.co.uk page 6/13



Tax & MOT check



Days left 217

MOT expiry date 19 September 2024

Full MOT history See MOT history

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NIK NIK
Plate since	
Current registration	AK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-05-06
Last registration	2023-09-20
Complete history	See info



Registration #1	2009-05-06	6 mi
Registration #2	2012-04-26	9.013 mi
Registration #3	2013-05-03	12.027 mi
Registration #4	2014-05-03	14.990 mi
Registration #5	2015-05-06	18.018 mi
Registration #6	2016-04-11	20.580 mi
Registration #7	2017-04-21	23.579 mi
Registration #8	2018-04-27	26.210 mi
Registration #9	2019-04-24	29.107 mi
Registration #10		11.177 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		111.7777 mg

More info >

page 12/13 CarCheck.co.uk



Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
60567	
50569	

Dimensions & weight

Width	2044 mm
Height	598 mm
Length	4278 mm
Kerb weight	1513 kg
Max. allowed weight	2240 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	9B12614

CarCheck.co.uk page 13/13