





report date: 2024-03-28

General information

| Make | KIA |
|---------------------|----------------|
| Model | RIO SR7 |
| Colour | Red |
| Year of manufacture | 2016 |
| Top speed | 104 mph |
| 0 - 60 mph | 12.6 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 83 BHP |
|-------------------------|---------------------|
| Max. torque | 122 Nm at 4.000 rpm |
| Engine capacity | 1.248 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 115 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history

Entry 2

Date 2022-01-28

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Da | te | 2021-07-14 |
|----|----|------------|
| | | |

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-02-01 |
|--------------------|------------|
| MOT pass rate | 70 % |
| MOT passed | 7 |
| Failed MOT tests | 3 |
| Total advice items | 22 |
| Total items failed | 4 |

| MOT #10 | | 2024-01-16 17:00 |
|-------------------------|---|----------------------|
| MOT test | number | 954327716561 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-02-01 |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Offside Rear Outer Brake pad(s) wearing thin Pad @ 3 mm (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice scored on | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened He inner $(1.1.14 (a) (ii))$ | eavily lipped outer, |

| MOT #9 | | 2023-01-09 15:13 |
|----------|---|------------------|
| MOT test | number | 712760330199 |
| Result | | ✓ Passed |
| Advice | Front Brake disc worn, but not excessively Both discs lipped (1.1.14 (a) (i)) | |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Rear Brake disc worn, but not excessively Both discs lipped (1.1.14 (a) (i)) | |

| MOT #8 | 2022-02-02 16:49 |
|-----------------|------------------|
| MOT test number | 573871123667 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2022-02-02 15:59

MOT test number 723501274065

Result X Failed

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #6 2021-07-14 14:36

MOT test number 171455783984

MOT #5 2020-10-19 07:51

MOT test number 127598453408

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 185/65/15 h (5.2.3 (e))

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2020-10-19 07:51

MOT test number 401734112560

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 185/65/15 h (5.2.3 (e))

Pass with rectification Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2019-10-23 11:12

MOT test number 167517301401

Result
✓ Passed

Advice Driver's view Items removed from driver's view prior to test Air Fresheners Removed From Rear View Mirror Prior To Test And Put Back After Test (3.1 (a) (ii))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 27% (1.2.1 (b) (i))

Minor Rear Windscreen wiper blade defective (3.4 (b) (i))

MOT #2 2019-10-23 08:24

MOT test number 740479477708

Result X Failed

Fail Brake master cylinder leaking (1.1.10 (b) (ii))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 27% (1.2.1 (b) (i))

Minor Rear Windscreen wiper blade defective (3.4 (b) (i))

Advice Driver's view Items removed from driver's view prior to test Air Fresheners Removed From Rear View Mirror Prior To Test And Put Back After Test (3.1 (a) (ii))

MOT #1 2019-01-21 09:05

MOT test number 525413533205

Result
✓ Passed

Advice Offside Rear Nail in tyre

Advice Nearside Rear tyre wearing on edges

Advice Offside Front tyre worn bald on inner edge

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 277 |
| MOT expiry date | 1 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| D | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

BP65UUZ

report date: 2024-03-28

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

See in this check if this KIA had different number plates.

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

**

*

More info >

CarCheck.co.uk page 9/12



BP65UUZ report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2016-01-23 |
| Last registration | 2024-01-16 |
| Complete history | See info |



| Registration #1 | 2016-01-23 | 14 mi |
|------------------|------------|-----------|
| Registration #1 | 2010-01-23 | 14 1111 |
| Registration #2 | 2019-01-21 | 35.630 mi |
| Registration #3 | 2019-10-23 | 46.880 mi |
| Registration #4 | 2019-10-23 | 46.883 mi |
| Registration #5 | 2020-10-19 | 62.037 mi |
| Registration #6 | 2020-10-19 | 62.037 mi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 0.777 66 |

More info >

CarCheck.co.uk page 11/12



BP65UUZ report date: 2024-03-28

Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 60482 | |
| 60501 | |
| 0566 | |
| 0567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 84% |
| Pedestrian | 46% |
| Safety systems | 86% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| Width | 1720 mm |
|---------------------|---------|
| Height | 1455 mm |
| Length | 4050 mm |
| Wheel base | 2570 mm |
| Kerb weight | 1207 kg |
| Max. allowed weight | 1560 kg |

Additional information

| Fuel tank capacity | 43 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/ |

Number of axles 2

Engine number G4LAFP137914