



PEUGEOT



LC64FSL

report date: 2024-03-28

General information

Make	PEUGEOT
Model	5008 HDI ACTIVE
Colour	Grey
Year of manufacture	2015
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-01-22
Pictures	2
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-06
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	26
Total items failed	9

MOT #102023-09-07 19:25

MOT test number707931485660

Result✓ Passed

Next expiry date2024-09-06

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Under tray fitted

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9**

2023-09-07 19:25

MOT test number

805302132491

Result**✗ Failed****Minor**

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification

Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice

Under tray fitted

Advice

Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Pass with rectification

Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice

Nearside Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor

Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #8

2022-08-30 17:42

MOT test number

485108712547

Result**✓ Passed****Advice**

Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Rear Child Seat fitted not allowing full inspection of adult belt All seats

Advice

Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice

Under tray fitted

Advice

Front Engine mounting damaged but not to excess (6.1.8 (a) (i))

Advice

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #7** 2022-08-30 17:08**MOT test number** 721050376867**Result** ✗ Failed**Advice** Front Engine mounting damaged but not to excess (6.1.8 (a) (i))**Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt All seats**Advice** Under tray fitted**MOT #6** 2021-09-07 10:23**MOT test number** 345807561766**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #5** 2020-10-21 14:56**MOT test number** 262133856318**Result** ✓ Passed**MOT #4** 2020-10-20 14:08**MOT test number** 297319209590**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage likely to become detached (5.3.3 (a) (ii))**Fail** Nearside Front Anti-roll bar linkage likely to become detached (5.3.3 (a) (ii))

**MOT #3** 2019-10-28 15:32**MOT test number** 487866809969**Result** ✓ Passed**MOT #2** 2019-10-28 12:07**MOT test number** 316340637571**Result** ✗ Failed**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #1** 2018-10-25 10:24**MOT test number** 460233059217**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-01-30
Last registration	2023-09-07
Complete history	See info



Registration #1	2015-01-30	18 mi
Registration #2	2018-10-25	27.605 mi
Registration #3	2019-10-28	39.568 mi
Registration #4	2019-10-28	39.568 mi
Registration #5	2020-10-20	53.458 mi
Registration #6	2020-10-21	53.469 mi
Registration #7	2023-09-07	53.477 mi
Registration #8	2023-09-07	53.477 mi
Registration #9	2023-09-07	53.477 mi
Registration #10	2023-09-07	53.477 mi
Registration #11	2023-09-07	53.477 mi
Registration #12	2023-09-07	53.477 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1837 mm
Height	1647 mm
Length	4529 mm
Wheel base	2727 mm
Kerb weight	1430 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	JBER0190221