



report date: 2024-03-29

General information

| | |
|---------------------|------------------------------|
| Make | VOLVO |
| Model | XC60 D5 R-DESIGN LUX NAV AWD |
| Colour | Blue |
| Year of manufacture | 2014 |
| Top speed | 121 mph |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 212 BHP |
| Max. torque | 440 Nm at 1.500 rpm |
| Engine capacity | 2.400 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 33.2 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 44.1 mpg |
| CO2 emission | 169 g/km |
| CO2 label | H |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-06 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-14 |
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 2 |

| | |
|------------------|------------------|
| MOT #10 | 2024-03-15 13:06 |
| MOT test number | 535391157111 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-14 |

| | |
|-----------------|------------------|
| MOT #9 | 2023-03-29 11:33 |
| MOT test number | 742962000327 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #8 | 2022-04-11 10:37 |
| MOT test number | 227299057281 |
| Result | ✓ Passed |
| Advice | Nearside Rear tyre starting to crack and perish between tread pattern |

| | |
|-----------------|------------------|
| MOT #7 | 2021-04-21 14:20 |
| MOT test number | 551386220394 |
| Result | ✓ Passed |

**MOT #6**

2021-04-14 11:55

MOT test number

285154799406

Result**✗ Failed**

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

2020-01-21 15:13

MOT test number

825687728887

Result**✓ Passed**

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

MOT #4

2020-01-21 11:26

MOT test number

323709079303

Result**✗ Failed**

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

MOT #3

2019-01-22 10:45

MOT test number

573897686869

Result**✓ Passed**



| | |
|-----------------|--|
| MOT #2 | 2018-01-23 10:21 |
| MOT test number | 140906974628 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-----------------|------------------|
| MOT #1 | 2017-01-26 11:40 |
| MOT test number | 544038717917 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
14 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 32 |
| MOT expiry date | 14 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2014-01-31 |
| Last registration | 2024-03-15 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-01-31 | 10 mi |
| Registration #2 | 2017-01-26 | 24.401 mi |
| Registration #3 | 2018-01-23 | 30.951 mi |
| Registration #4 | 2019-01-22 | 36.458 mi |
| Registration #5 | 2020-01-21 | 42.036 mi |
| Registration #6 | 2020-01-21 | 42.036 mi |
| Registration #7 | 2020-01-21 | 42.036 mi |
| Registration #8 | 2020-01-21 | 42.036 mi |
| Registration #9 | 2020-01-21 | 42.036 mi |
| Registration #10 | 2020-01-21 | 42.036 mi |
| Registration #11 | 2020-01-21 | 42.036 mi |
| Registration #12 | 2020-01-21 | 42.036 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 94% |
| Children | 79% |
| Pedestrian | 48% |
| Safety systems | 86% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2120 mm |
| Height | 1713 mm |
| Length | 4644 mm |
| Wheel base | 2774 mm |
| Kerb weight | 1862 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1522159 |