





report date: 2024-03-28

# General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Red
Year of manufacture	2012
Top speed	98 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Semi-Automatic

# Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

# Entry 1

Date 2021-09-28

Pictures 31

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



FT62GZH report date: 2024-03-28

MOT history

MOT expiry date	2024-09-30
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #11	2023-09-22 15:22
MOT test number	347965196961
Result	✓ Passed
Next expiry date	2024-09-30

MOT #10		2022-09-13 14:51
MOT test	number	246678607417
Result		✓ Passed
Advice	Offside Brake pipe corroded, covered in grease or other material front to re-	ar (1.1.11 (c))
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))	
Advice	Advice Items removed from driver's view prior to test	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in exce	ssive movement (5.3.4

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9	2022-09-13 14:51	
MOT test number	363578574000	
Result	<b>X</b> Failed	
Advice Items removed from driver's view prior to test		
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in ex (5.3.4 (a) (i))	cessive movement	
Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification Offside Headlamp aim projected beam image is obviously	y incorrect (4.1.2 (c))	
Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Offside Brake pipe corroded, covered in grease or other material front to re	ear (1.1.11 (c))	

MOT #8	2021-10-01 16:09
MOT test number	818298275068
Result	✓ Passed
MOT #7	2021-01-07 09:30
<b>MOT test number</b> 31973980243	
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Vehicles internal headlight adjuster altered to recheck lights	

MOT #6	2020-01-08 13:31
MOT test number	538264375805
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2019-01-04 14:24

**MOT test number** 595523459997

**Result** ✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #4 2017-12-28 10:03

**MOT test number** 528250653769

MOT #3 2017-12-28 10:03

**MOT test number** 623110033052

**Result** X Failed

**Pass with rectification** Headlamp aim too low (1.8)

**Pass with rectification** Front registration plate faded (6.3.1d)

MOT #2 2017-01-06 09:30

MOT test number 346448169681

**Advice** Offside Rear front to rear brake pipe slightly corroded

**Advice** Both front suspension arm rear bushes perishing

MOT #1 2016-01-19 11:54

**MOT test number** 707127267999

**Result** ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

# Tax & MOT check





Expires: 30 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	30 September 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



FT62GZH report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates furthe scinors

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >


CarCheck.co.uk page 10/12



FT62GZH report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-12-07
Last registration	2023-09-22
Complete history	See info



Registration #1	2012-12-07	8 mi
Registration #2	2016-01-19	33.902 mi
Registration #3	2017-01-06	37.255 mi
Registration #4	2017-12-28	40.413 mi
Registration #5	2017-12-28	40.413 mi
Registration #6	2019-01-04	45.729 mi
Registration #7	2020-01-08	48.381 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	925 kg
Max. allowed weight	1190 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	7232258

CarCheck.co.uk page 12/12