



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	White
Year of manufacture	2012
Top speed	117 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	160 g/km
CO2 label	G





## MOT history

MOT expiry date	2025-02-10
MOT pass rate	100 %
MOT passed	9
Failed MOT tests	0
Total advice items	20
Total items failed	0

MOT #9	2024-02-09 12:53
MOT test number	887147226524
Result	✓ Passed
Next expiry date	2025-02-10

MOT #8	2023-02-10 15:04
MOT test number	241320197449
Result	✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #7	2022-02-11 12:53
MOT test number	927038028784
Result	✓ Passed

**MOT #6**

2020-12-15 10:09

**MOT test number**

508152896864

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Rear Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Exhaust system corroded

**MOT #5**

2019-12-03 14:59

**MOT test number**

621027866530

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust system corroded
- Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #4**

2018-12-17 14:29

**MOT test number**

531974764367

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))
- Advice** Exhaust system corroded



MOT #3	2017-12-15 09:55
MOT test number	474476972723
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2	2016-12-29 09:30
MOT test number	861126712073
Result	✓ Passed

MOT #1	2015-11-24 13:40
MOT test number	800397235443
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
10 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	10 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YS62FYR
Plate since	2024-03-29
Current registration	 YS62FYR
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2012-12-17
Last registration	2024-02-09
Complete history	<a href="#">See info</a>



Registration #1	2012-12-17	6 mi
Registration #2	2015-11-24	18.264 mi
Registration #3	2016-12-29	24.916 mi
Registration #4	2017-12-15	26.999 mi
Registration #5	2018-12-17	29.830 mi
Registration #6	2019-12-17	31.777 mi
Registration #7	2020-12-17	33.724 mi
Registration #8	2021-12-17	35.671 mi
Registration #9	2022-12-17	37.618 mi
Registration #10	2024-02-09	39.565 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1761 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	172829K