



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	Silver
Year of manufacture	-
Top speed	72 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg





Internet history

Entry 1

Date	2021-09-21
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #17</b>	2022-05-19 12:58
<b>MOT test number</b>	576625111712
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-05-18

<b>MOT #16</b>	2022-05-17 14:12
<b>MOT test number</b>	926034259000
<b>Result</b>	✗ Failed

**Advice** Nearside Front Play in steering rack inner joint(s)

**Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Rear Suspension arm corroded and seriously weakened Spring cup (5.3.3 (b) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

<b>MOT #15</b>	2021-05-18 11:27
<b>MOT test number</b>	464142856853
<b>Result</b>	✓ Passed

<b>MOT #14</b>	2021-05-18 11:27
<b>MOT test number</b>	157823685397
<b>Result</b>	✗ Failed

**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #13**

2019-05-29 16:34

**MOT test number**

408419399955

**Result**

✓ Passed

- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement  
Trailing arm (5.3.4 (a) (i))
- Advice** Handbrake release button damaged. Still operation
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement  
Trailing arm (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2018-05-30 15:20

**MOT test number**

477331348390

**Result**

✓ Passed

- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Steering arm has slight movement in ball joint
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Steering arm has slight movement in ball joint
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #11**

2017-05-31 06:40

**MOT test number**

671017462530

**Result**

✓ Passed

**MOT #10**

2016-09-20 13:22

**MOT test number**

365092705823

**Result**

✓ Passed

- Advice** Exhaust system slightly corroded
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #9**

2015-09-17 08:35

**MOT test number**

437770806055

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Windscreen wipers starting to smear but still clearing screen
- Advice** Offside rear tyre starting to deteriorate
- Advice** Both rear tyres have wear to inner edges of tread

**MOT #8**

2014-09-17 15:17

**MOT test number**

767280564216

**Result**

✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Both windscreen wipers starting to smear but still clearing windscreen
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #7** 2014-09-17 15:17**MOT test number** 715680064296**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (1.8)**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Offside Headlamp aim too low (1.8)**Notice** Both windscreen wipers starting to smear but still clearing windscreen**MOT #6** 2013-09-19 12:05**MOT test number** 556582363258**Result** ✓ Passed**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2013-09-19 11:14**MOT test number** 846552763242**Result** ✗ Failed**Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Centre Stop lamp not working (1.2.1b)**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2012-09-21 14:07**MOT test number** 118515362222**Result** ✓ Passed



MOT #3	2012-09-18 09:56
MOT test number	666302062290
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2	2011-09-21 14:39
MOT test number	215904861208
Result	✓ Passed

MOT #1	2010-09-21 10:08
MOT test number	401884360280
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-21
Last registration	2022-05-19
Complete history	<a href="#">See info</a>



Registration #1	2007-09-21	23 mi
Registration #2	2010-09-21	25.949 mi
Registration #3	2011-09-21	37.823 mi
Registration #4	2012-09-18	49.258 mi
Registration #5	2012-09-21	49.347 mi
Registration #6	2013-09-19	62.557 mi
Registration #7	2013-09-19	62.557 mi
Registration #8	2014-09-17	76.400 mi
Registration #9	2015-09-17	92.114 mi
Registration #10	2016-09-17	108.000 mi
Registration #11	2017-09-17	124.000 mi
Registration #12	2018-09-17	140.000 mi
Registration #13	2019-09-17	156.000 mi
Registration #14	2020-09-17	172.000 mi
Registration #15	2021-09-17	188.000 mi
Registration #16	2022-05-19	204.000 mi
Registration #17	2022-05-19	204.000 mi
Registration #18	2022-05-19	204.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

