



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI S 5STR
Colour	Grey
Year of manufacture	2005
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-24
Pictures	2
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-23
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	6
Total items failed	18

MOT #21	2024-02-24 12:31
MOT test number	367606661928
Result	✓ Passed
Next expiry date	2025-02-23

MOT #20	2022-12-30 12:26
MOT test number	371668282131
Result	✓ Passed

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #19**

2022-12-22 12:25

MOT test number

100531107974

Result**✗ Failed**

- Fail** Rear Shock absorbers has a serious fluid leak both sides (5.3.2 (b))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))
- Fail** Offside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))
- Fail** Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt both sides (5.3.4 (b) (ii))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Front Suspension arm pin or bush excessively worn both sides rear bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Central Exhaust system insecure exhaust clamp (6.1.2 (a))

MOT #18

2021-11-20 11:47

MOT test number

840803706213

Result**✓ Passed**

- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #17

2020-08-26 10:16

MOT test number

987021897241

Result**✓ Passed****MOT #16**

2019-05-22 14:42

MOT test number

179945120017

Result**✓ Passed**

**MOT #15** 2019-05-21 11:05**MOT test number** 500652330383**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**MOT #14** 2018-05-21 17:15**MOT test number** 363282801391**Result** ✓ Passed**MOT #13** 2018-05-21 09:32**MOT test number** 948214042879**Result** ✗ Failed**Fail** Nearside Front Service brake excessively binding (1.2.1 (f))**MOT #12** 2017-05-23 12:09**MOT test number** 446651675608**Result** ✓ Passed**MOT #11** 2017-05-22 14:40**MOT test number** 821125571329**Result** ✗ Failed**Fail** Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside front brake binding (3.7.B.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #10** 2016-05-19 13:41**MOT test number** 510383551153**Result** ✓ Passed**MOT #9** 2016-05-18 09:06**MOT test number** 800601347485**Result** ✗ Failed

- Fail** Nearside front brake binding (3.7.B.1)
- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)

MOT #8 2015-05-22 09:41**MOT test number** 248432145463**Result** ✓ Passed**MOT #7** 2014-05-19 09:46**MOT test number** 385239634104**Result** ✓ Passed**MOT #6** 2013-05-18 09:14**MOT test number** 279118433125**Result** ✓ Passed**MOT #5** 2012-05-19 10:12**MOT test number** 426540742194**Result** ✓ Passed**MOT #4** 2011-05-21 10:01**MOT test number** 425591441184**Result** ✓ Passed



MOT #3	2010-05-15 09:35
MOT test number	443625230106
Result	✓ Passed
<div>NoticeAll brake pads low</div>	

MOT #2	2009-05-16 11:44
MOT test number	292006639410
Result	✓ Passed

MOT #1	2008-05-14 14:18
MOT test number	263325238477
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
23 February 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	23 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KY05TNZ
Plate since	2024-03-29
Current registration	 KY05TNZ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-05-14
Last registration	2024-02-24
Complete history	See info



Registration #1	2005-05-14	11 mi
Registration #2	2008-05-14	32.880 mi
Registration #3	2009-05-16	45.146 mi
Registration #4	2010-05-15	58.226 mi
Registration #5	2011-05-21	71.061 mi
Registration #6	2012-05-19	84.195 mi
Registration #7	2013-05-18	90.205 mi
Registration #8	2014-05-19	95.189 mi
Registration #9	2015-05-22	98.800 mi
Registration #10	2016-05-18	102.715 mi
Registration #11	2016-05-19	102.723 mi
Registration #12	2017-05-22	114.807 mi
Registration #13	2018-05-22	126.891 mi
Registration #14	2019-05-22	138.975 mi
Registration #15	2020-05-22	151.059 mi
Registration #16	2021-05-22	163.143 mi
Registration #17	2022-05-22	175.227 mi
Registration #18	2023-05-22	187.311 mi
Registration #19	2024-02-24	199.395 mi
Registration #20	2024-02-24	211.479 mi
Registration #21	2024-02-24	223.563 mi
Registration #22	2024-02-24	235.647 mi
Registration #23	2024-02-24	247.731 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKC 732958