



report date: 2024-03-29

General information

Make	HONDA
Model	FR-V CTDI SPORT
Colour	Black
Year of manufacture	2006
Top speed	103 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.204 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-01-28
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-02-20
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	29
Total items failed	4

MOT #18 2024-02-21 16:58

MOT test number 598923138893

Result ✓ Passed

Next expiry date 2025-02-20

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #17 2023-01-10 11:48

MOT test number 600453959931

Result ✓ Passed

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #16** 2023-01-09 14:53**MOT test number** 794227783557**Result** ✗ Failed**Fail** Nearside Rear Outer Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #15** 2022-01-28 09:54**MOT test number** 988412480635**Result** ✓ Passed**Advice** Nearside Rear Sill slightly damaged**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**MOT #14** 2022-01-27 15:51**MOT test number** 658209247092**Result** ✗ Failed**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**Fail** Rear Stop lamp(s) not working X2 (4.3.1 (a) (ii))**Fail** Offside Rear Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Sill slightly damaged**Fail** Front Position lamp not working Both (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2021-01-07 14:20**MOT test number** 541697880448**Result** ✓ Passed**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #12** 2020-01-16 10:14**MOT test number** 651833345875**Result** ✓ Passed**MOT #11** 2019-01-12 10:48**MOT test number** 642229692602**Result** ✓ Passed**MOT #10** 2018-01-22 12:53**MOT test number** 425348458995**Result** ✓ Passed**Advice** Offside rear anti roll bar link has slight play**MOT #9** 2017-01-16 12:05**MOT test number** 834030146874**Result** ✓ Passed**MOT #8** 2016-05-20 10:08**MOT test number** 167278400719**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2015-05-12 16:57**MOT test number** 607992835195**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-05-15 11:53**MOT test number** 295385434162**Result** ✓ Passed**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2013-05-10 11:54**MOT test number** 548200533190**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #4** 2012-05-15 15:30**MOT test number** 619316732185**Result** ✓ Passed**Notice** Sidewall/tread cracking rear tyres**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2011-05-17 15:37**MOT test number** 237247931462**Result** ✓ Passed**Notice** Wear front tyres



MOT #2	2010-05-18 11:49
MOT test number	300148530196
Result	✓ Passed
<div>Notice</div> Child seat fitted not allowing full inspection of adult belt	

MOT #1	2009-05-20 11:02
MOT test number	112410749171
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
20 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	20 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-05-24
Last registration	2024-02-21
Complete history	<a href="#">See info</a>



Registration #1	2006-05-24	25 mi
Registration #2	2009-05-20	9.442 mi
Registration #3	2010-05-18	13.285 mi
Registration #4	2011-05-17	19.763 mi
Registration #5	2012-05-15	25.614 mi
Registration #6	2013-05-10	31.810 mi
Registration #7	2014-05-15	40.716 mi
Registration #8	2015-05-12	49.202 mi
Registration #9	2016-05-20	59.815 mi
Registration #10	2017-01-16	62.265 mi
Registration #11	2018-05-20	75.377 mi
Registration #12	2019-05-20	75.377 mi
Registration #13	2020-05-20	75.377 mi
Registration #14	2021-05-20	75.377 mi
Registration #15	2022-05-20	75.377 mi
Registration #16	2023-05-20	75.377 mi
Registration #17	2024-02-21	75.377 mi
Registration #18	2024-02-21	75.377 mi
Registration #19	2024-02-21	75.377 mi
Registration #20	2024-02-21	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1584 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	N22A11503858