



report date: 2024-03-29

General information

| | |
|---------------------|------------------------|
| Make | FORD |
| Model | FOCUS C-MAX TITANIUM D |
| Colour | Silver |
| Year of manufacture | - |
| Top speed | 126 mph |
| 0 - 60 mph | 9.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 134 BHP |
| Max. torque | 340 Nm at 2.000 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 51.4 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-18 |
| Pictures | 4 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|------------------------|---|
| MOT #18 | 2021-12-21 12:21 |
| MOT test number | 695365399148 |
| Result | ✗ Failed |
| Fail | Nearside Rear Service brake excessively binding (1.2.1 (f)) |
| Fail | Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b)) |
| Advice | Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| Advice | Offside Front Coil spring corroded (5.3.1 (b) (i)) |

| | |
|------------------------|------------------|
| MOT #17 | 2020-12-16 14:30 |
| MOT test number | 583446367435 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #16 | 2019-05-24 08:43 |
| MOT test number | 314858197701 |
| Result | ✓ Passed |

| | |
|------------------------|--|
| MOT #15 | 2018-06-05 10:03 |
| MOT test number | 937343073045 |
| Result | ✓ Passed |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) |

| | |
|------------------------|--|
| MOT #14 | 2017-06-19 09:14 |
| MOT test number | 751623959858 |
| Result | ✓ Passed |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |

**MOT #13** 2017-06-19 09:14**MOT test number** 539345633999**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #12** 2016-06-20 13:26**MOT test number** 450862813539**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #11** 2015-06-09 15:19**MOT test number** 229700165406**Result** ✓ Passed**MOT #10** 2014-06-20 16:50**MOT test number** 328841174187**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #9** 2013-01-08 09:25**MOT test number** 998518003023**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2013-01-04 11:50**MOT test number** 879724803033**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2012-01-10 09:13**MOT test number** 116770412009**Result** ✓ Passed**MOT #6** 2012-01-06 14:55**MOT test number** 508256302030**Result** ✗ Failed**Advice** Nearside Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #5** 2011-01-06 18:08**MOT test number** 607976801022**Result** ✓ Passed**MOT #4** 2011-01-06 18:08**MOT test number** 247986401063**Result** ✗ Failed**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



| | |
|-----------------|------------------|
| MOT #3 | 2010-01-14 12:24 |
| MOT test number | 722814510040 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #2 | 2009-01-08 11:37 |
| MOT test number | 970748409013 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2007-12-11 14:45 |
| MOT test number | 964195047317 |
| Result | ✓ Passed |

Notice Front tyres bald inner edge



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | ET54TUA |
| Plate since | 2024-03-29 |
| Current registration | ET54TUA |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2005-01-31 |
| Last registration | 2021-12-21 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2005-01-31 | 26 mi |
| Registration #2 | 2007-12-11 | 33.926 mi |
| Registration #3 | 2009-01-08 | 52.690 mi |
| Registration #4 | 2010-01-14 | 70.326 mi |
| Registration #5 | 2011-01-06 | 85.507 mi |
| Registration #6 | 2012-01-06 | 93.167 mi |
| Registration #7 | 2012-01-10 | 93.169 mi |
| Registration #8 | 2013-01-04 | 100.001 mi |
| Registration #9 | 2013-01-08 | 100.023 mi |
| Registration #10 | 2014-06-20 | 111.189 mi |
| Registration #11 | 2015-01-01 | 121.217 mi |
| Registration #12 | 2015-01-01 | 121.217 mi |
| Registration #13 | 2015-01-01 | 121.217 mi |
| Registration #14 | 2015-01-01 | 121.217 mi |
| Registration #15 | 2015-01-01 | 121.217 mi |
| Registration #16 | 2015-01-01 | 121.217 mi |
| Registration #17 | 2015-01-01 | 121.217 mi |
| Registration #18 | 2015-01-01 | 121.217 mi |
| Registration #19 | 2015-01-01 | 121.217 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1991 mm |
| Height | 1447 mm |
| Length | 4382 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1276 kg |
| Max. allowed weight | 1895 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|---------------|---------|
| Engine number | 5U29666 |
|---------------|---------|