





report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO DYNAMIC
Colour	Blue
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	128 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/14



significantly reduced outer sill (6.1.1 (c) (i))

YX08WVR

report date: 2024-03-28

MOT history

MOT expiry date	2025-04-06
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	23
Total items failed	25

MOT #23	2024-04-05 13:09
MOT test number	348229608680
Result	✓ Passed
Next expiry date	2025-04-06

MOT #	222	2024-04-03 16:01
MOT to	est number	774236934032
Result		× Failed
Fail	Rear Exhaust system insecure rubber hanger broken (6.1.2 (a))	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Rear Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced outer sill (6.1.1 (c) (i))		
Fail	Nearside Rear Integral body structure corroded to the extent that the rigidity of	f the assembly is

MOT #21	2023-04-05 15:40
MOT test number	238072401926
Result	✓ Passed

CarCheck.co.uk page 2/14



MOT #20

YX08WVR
report date: 2024-03-28

2023-04-05 11:09

MOT test number 439700316656

Result X Failed

Fail Nearside Rear Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Rear Exhaust silencer insecure rubber hanger about to snap (8.1.1 (b) (i))

MOT #19 2022-03-26 12:19

MOT test number 765356754844

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Oil leak, but not excessive both drive shaft seals (8.4.1 (a) (i))

MOT #18 2022-03-19 11:10

MOT test number 909922345254

Result X Failed

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Offside Front Suspension arm pin or bush excessively worn rear bush debonded (5.3.4 (a) (i))

Advice Oil leak, but not excessive both drive shaft seals (8.4.1 (a) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn rear bush debonded (5.3.4 (a) (i))

MOT #17 2021-04-07 13:56

MOT test number 703541127046

Result

Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #16

MOT test number

899238929296

Result

Fail Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d))

Fail Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d))

 MOT #15
 2020-02-08 09:02

 MOT test number
 609937580980

 Result
 ✓ Passed

 MOT #14
 2019-01-19 13:33

 MOT test number
 798138280217

 MOT #13
 2019-01-19 09:19

 MOT test number
 107881216206

 Result
 ★ Failed

Fail Front Exhaust has a major leak of exhaust gases flexi broken (6.1.2 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Front Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/14



YX08WVR
report date: 2024-03-28

MOT #12 2018-01-27 08:58

MOT test number 372981168494

Result ✓ Passed

Advice Exhaust has a minor leak of exhaust gases flexi pipe (7.1.2)

Advice All tyres on 3mm of tread (205/55r16)

Advice Rear silencer deteriorated

Advice Offside front tyre worn on inner edge

MOT #11 2017-01-27 14:42

MOT test number 513686323023

Result \square Passed

Advice Rear silencer deteriorated

Advice Offside front tyre worn on inner edge (205/55r16)

MOT #10 2017-01-21 08:51

MOT test number 330129285850

Result X Failed

Advice Rear silencer deteriorated

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Advice Offside front tyre worn on inner edge (205/55r16)

MOT #9 2016-01-30 14:43

MOT test number 903057006189

Result

Passed

Advice Exhaust has a minor leak of exhaust gases mid section flexi (7.1.2)

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #8	2016-01-30 08:48
MOT test number	541200778554
Result	× Failed
Advice Exhaust has a minor leak of exhaust gases mid section flexi (7.1.2)	
Advice Front Brake pad(s) wearing thin approx. 90% worn (3.5.1g)	
Fail Nearside front brake excessively fluctuating (3.7.B.3)	
Fail Offside Front coil spring broken (2.4.C.1a)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail Offside front brake excessively fluctuating (3.7.B.3)	
Fail Nearside Front coil spring broken (2.4.C.1a)	

MOT #7		2015-01-24 08:46
MOT test	number	867464825040
Result		✓ Passed
Notice	Nearside front tyre on 2mm tread	
Notice	Offside front tyre on 2mm tread (205/55r16)	
Notice	Front brake pads 75% worn	

MOT #6	2014-01-25 08:47
MOT test number	946565724040
Result	✓ Passed
Notice Nearside rear brake binding slightly	

MOT #5	2013-01-19 10:54
MOT test number	866759113080
Result	✓ Passed

CarCheck.co.uk page 6/14



YX08WVR report date: 2024-03-28

MOT #4 2013-01-19 09:15

MOT test number 528529013092

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3 2012-02-11 08:50

MOT test number 859852742006

Result \(\sqrt{Passed} \)

MOT #2 2011-09-14 12:19

MOT test number 937117251297

Result X Failed

Fail Brake operation stored air pressure or vacuum depletes when ancillary equipment is operated (3.3.E.4)

MOT #1 2011-02-16 15:00

MOT test number 326197841061

CarCheck.co.uk page 7/14



YX08WVR report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	6 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



YX08WVR report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

More info >

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this FIAT had different number plates. nber of plates funda scincos

CarCheck.co.uk page 11/14



YX08WVR report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2008-03-31
Last registration	2024-04-05
Complete history	See info



Registration #2 2011-02-16 4.587 mi Registration #3 2011-09-14 5.121 mi Registration #4 2012-02-11 6.930 mi Registration #5 2013-01-19 10.638 mi Registration #6 2013-01-19 10.638 mi Registration #7 2014-01-25 15.296 mi Registration #8 2015-01-24 21.040 mi Registration #9 2016-01-30 25.903 mi Registration #10 2016-01-30 25.903 mi Registration #11 2017-01-21 30.386 mi			
Registration #3 2011-09-14 5.121 mi Registration #4 2012-02-11 6.930 mi Registration #5 2013-01-19 10.638 mi Registration #6 2013-01-19 10.638 mi Registration #7 2014-01-25 15.296 mi Registration #8 2015-01-24 21.040 mi Registration #9 2016-01-30 25.903 mi Registration #10 2016-01-30 25.903 mi Registration #11 2017-01-21 30.386 mi Registration #12 2017-01-27 30.492 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #1	2008-03-31	29 mi
Registration #4 2012-02-11 6.930 mi Registration #5 2013-01-19 10.638 mi Registration #6 2013-01-19 10.638 mi Registration #7 2014-01-25 15.296 mi Registration #8 2015-01-24 21.040 mi Registration #9 2016-01-30 25.903 mi Registration #10 2016-01-30 25.903 mi Registration #11 2017-01-21 30.386 mi Registration #12 2017-01-27 30.492 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #19 Registration #20 Registration #22 Registration #22 Registration #22 Registration #23	Registration #2	2011-02-16	4.587 mi
Registration #5 2013-01-19 10.638 mi Registration #6 2013-01-19 10.638 mi Registration #7 2014-01-25 15.296 mi Registration #8 2015-01-24 21.040 mi Registration #9 2016-01-30 25.903 mi Registration #10 2016-01-30 25.903 mi Registration #11 2017-01-21 30.386 mi Registration #12 2017-01-27 30.492 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Registration #22 Registration #23	Registration #3	2011-09-14	5.121 mi
Registration #6 2013-01-19 10.638 mi Registration #7 2014-01-25 15.296 mi Registration #8 2015-01-24 21.040 mi Registration #9 2016-01-30 25.903 mi Registration #10 2016-01-30 25.903 mi Registration #11 2017-01-21 30.386 mi Registration #12 2017-01-27 30.492 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #4	2012-02-11	6.930 mi
Registration #7 Registration #8 2015-01-24 2016-01-30 25.903 mi Registration #10 2016-01-30 25.903 mi Registration #11 2017-01-21 30.386 mi Registration #12 2017-01-27 30.492 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #5	2013-01-19	10.638 mi
Registration #8 2015-01-24 21.040 mi Registration #9 2016-01-30 25.903 mi Registration #10 2016-01-30 25.903 mi Registration #11 2017-01-21 30.386 mi Registration #12 2017-01-27 30.492 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #6	2013-01-19	10.638 mi
Registration #9 2016-01-30 25.903 mi Registration #10 2016-01-30 25.903 mi Registration #11 2017-01-21 30.386 mi Registration #12 2017-01-27 30.492 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #7	2014-01-25	15.296 mi
Registration #10 2016-01-30 25.903 mi Registration #11 2017-01-21 30.386 mi Registration #12 2017-01-27 30.492 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #23	Registration #8	2015-01-24	21.040 mi
Registration #11 2017-01-21 30.386 mi Registration #12 2017-01-27 30.492 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #9	2016-01-30	25.903 mi
Registration #12 2017-01-27 30.492 mi Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #10	2016-01-30	25.903 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #11	2017-01-21	30.386 mi
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #12	2017-01-27	30.492 mi
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21 Registration #22 Registration #23	Registration #13		D.777 es
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #14		11.777 es
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #15		9.79 es
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #16		11.777 es
Registration #19 Registration #20 Registration #21 Registration #22 Registration #23	Registration #17		D.777 es
Registration #20 Registration #21 Registration #22 Registration #23	Registration #18		11.777 es
Registration #21 Registration #22 Registration #23	Registration #19		D.777 es
Registration #22 Registration #23	Registration #20		11.777 es
Registration #23	Registration #21		11.777 es
	Registration #22		11.777 es
Registration #24	Registration #23		11.777 es
	Registration #24		0.07 44

More info >



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	58
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles2Engine number1267536