





report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO 2900 DYNAMIC S/S L1H1 2900 DYNAMIC S/S
Colour	White
Year of manufacture	2020
Top speed	90 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	270 Nm at 1.600 rpm
Engine capacity	1.499 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	44.8 mpg
CO2 emission	131 g/km
CO2 label	E



CarCheck.co.uk page 1/10



Internet history

Entry 2

Date 2023-10-30

Pictures 28

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date	2022-07-03
Pictures	23

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2025-04-02
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	4
Total items failed	3

MOT #5	2024-04-03 07:48
MOT test number	416874299659
Result	✓ Passed
Next expiry date	2025-04-02

MOT #4	2024-03-28 15:26
MOT test number	172936937551
Result	X Failed
Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Offside Side repeater not working (4.4.1 (a) (ii))	
Advice Front Brakes imbalanced requirements only just met. It would appear that requires adjustment or repair. (1.2.1 (b) (i))	the braking system

MOT #3	2023-11-08 12:05
MOT test number	977821800473
Result	✓ Passed

MOT #2	2023-04-24 15:49
MOT test number	482385226253
Result	✓ Passed
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/10



MOT #1 2023-04-24 09:26

MOT test number 751292985567

Result

x Failed

Minor

Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/10



DL69XLT

report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	IIK SIE
Plate since	
Current registration	UK ZIS
Plate since	
	More info

CarCheck.co.uk page 7/10



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2020-01-31
Last registration	2024-04-03
Complete history	See info



Registration #1	2020-01-31	8 mi
Registration #2		11.777 es
Registration #3	2023-04-24	79.708 mi
Registration #4	2023-04-24	79.708 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 9/10



Dimensions & weight

Width	1920 mm
Height	1940 mm
Length	4959 mm
Kerb weight	1660 kg
Max. allowed weight	2830 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	YH01-31203

CarCheck.co.uk page 10/10