





report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	White
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-09-02

Pictures 29

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-08-22
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-06-15
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	20
Total items failed	0

MOT #7	2023-06-13 09:15
MOT test number	164929474554
Result	✓ Passed
Next expiry date	2024-06-15
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))
Advice Offside Front door trim secured with tape	
Minor Nearside Front Track rod end ball joint dust cover damaged or deterioral ingress of dirt (2.1.3 (g) (i))	ted, but preventing the

MOT #6	2022-06-14 15:36
MOT test number	495179105388
Result	✓ Passed
Advice Offside Rear Brakes imbalanced requirements only just met. It would appear system requires adjustment or repair. (1.2.1 (b) (i))	that the braking
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



MOT #5

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2019-10-25 09:50 **MOT** test number 418840919608 Result Passed **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #2	2018-10-04 14:02
MOT test number	262246590714
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT #1 2017-10-14 09:51

MOT test number 821692899851

Result ✓ Passed

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Correct registration	UK NE
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-10-31
Last registration	2023-06-13
Complete history	See info



Registration #1	2014-10-31	24 mi
Registration #2	2017-10-14	30.539 mi
Registration #3	2018-10-04	38.020 mi
Registration #4	2019-10-25	46.811 mi
Registration #5	2020-10-13	53.504 mi
B 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Registration #6		n
Registration #6 Registration #7		11.777 es
•		11,777 ea 11,777 ea
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number D4FDEZ258681