



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC4 8 SEATS
Colour	Black
Year of manufacture	2003
Top speed	106 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	343 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	32.5 mpg
Consumption combined	27.2 mpg
CO2 emission	277 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-12-28
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-08
MOT pass rate	64 %
MOT passed	18
Failed MOT tests	10
Total advice items	64
Total items failed	14

MOT #28	2023-05-09 09:41
MOT test number	754046280341
Result	✓ Passed
Next expiry date	2024-05-08
Advice	Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #27	2022-05-05 09:45
MOT test number	430821123259
Result	✓ Passed
Advice	Offside Inner sill corroded
Advice	Underside corrosion
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #26	2021-06-28 13:18
MOT test number	499320826715
Result	✓ Passed

**MOT #25** 2021-06-28 10:11**MOT test number** 416836471895**Result** ✗ Failed**MAJOR** Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #24** 2020-07-17 13:13**MOT test number** 877652217014**Result** ✓ Passed**Advice** Offside headlight has poor beam image**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Nail in tyre**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords outer wall (5.2.3 (d) (i))

**MOT #23**

2020-07-15 08:46

MOT test number

526807466501

Result**✗ Failed**

- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Brake pipe excessively corroded both front to rear at rear by brake hoses (1.1.11 (c))
- Advice** Offside headlight has poor beam image
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords outer wall (5.2.3 (d) (i))
- MAJOR** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #22

2019-07-16 12:54

MOT test number

724379060015

Result**✓ Passed**

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material to rear x2 (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Fuel pipes rusty

**MOT #21**

2018-07-18 09:38

MOT test number

473860713160

Result

✓ Passed

- Advice** A/C leaking
- Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Wipers starting to smear
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))

MOT #20

2018-07-18 09:38

MOT test number

880675249531

Result

✗ Failed

- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** A/C leaking
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Wipers starting to smear
- Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))

MOT #19

2017-07-12 10:51

MOT test number

530985392123

Result

✓ Passed

- Advice** Offside Rear shock absorber casing corroded
- Advice** Nearside Rear shock absorber casing corroded

**MOT #18**

2016-07-13 07:29

MOT test number

836278768223

Result

✓ Passed

Advice Front front brake fluctuating, but not excessively (3.7.B.3)**Advice** Both rear shock housings corroded not damaged or leaking**MOT #17**

2016-07-12 14:45

MOT test number

258228781524

Result

✗ Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Both rear shock housings corroded not damaged or leaking**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front front brake fluctuating, but not excessively (3.7.B.3)**MOT #16**

2015-07-22 12:02

MOT test number

325543705213

Result

✓ Passed

Notice Both rear shock absorber casings corroded

**MOT #15**

2015-07-22 12:02

MOT test number

195333705271

Result

✗ Failed

Notice Both rear shock absorber casings corroded**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #14**

2014-07-23 08:23

MOT test number

746724804242

Result

✓ Passed

Advice Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #13**

2014-07-23 08:23

MOT test number

529764604272

Result

✗ Failed

Advice Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Pass with rectification** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #12**

2013-08-14 15:20

MOT test number

387006323477

Result

✓ Passed

**MOT #11** 2013-08-09 10:52**MOT test number** 245201223261**Result** ✗ Failed

Advice Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Fail Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #10 2012-07-31 10:26**MOT test number** 586913712260**Result** ✓ Passed**MOT #9** 2012-07-28 10:40**MOT test number** 796210512287**Result** ✗ Failed

Fail Nearside Seat belt retracting mechanism defective (5.2.5b)

Fail Offside Rear Seat belt retracting mechanism defective (5.2.5b)

Fail Offside Seat belt retracting mechanism defective (5.2.5b)

MOT #8 2011-08-18 11:37**MOT test number** 316740431407**Result** ✓ Passed**MOT #7** 2011-08-18 11:37**MOT test number** 838120631215**Result** ✗ Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #6** 2010-08-18 10:34**MOT test number** 404440430258**Result** ✓ Passed**MOT #5** 2009-08-05 09:56**MOT test number** 541627119264**Result** ✓ Passed**MOT #4** 2008-08-08 10:37**MOT test number** 123911428296**Result** ✗ Failed**Notice** Only able to check rear/rear seat belt webbing**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** Both front tyres worn slightly on the insides**Notice** Rear tyres showing signs of weathering**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #3** 2008-08-08 10:37**MOT test number** 403801128287**Result** ✓ Passed**Notice** Only able to check rear/rear seat belt webbing**Notice** Rear tyres showing signs of weathering**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** Both front tyres worn slightly on the insides



MOT #2	2007-08-23 11:23
MOT test number	330175137226
Result	✓ Passed
MOT #1	2006-08-18 12:10
MOT test number	224410136272
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
8 May 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	8 May 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-08-21
Last registration	2023-05-09
Complete history	See info



Registration #1	2003-08-21	24 mi
Registration #2	2006-08-18	28.044 mi
Registration #3	2007-08-23	36.979 mi
Registration #4	2008-08-08	45.482 mi
Registration #5	2009-08-05	54.909 mi
Registration #6	2010-08-18	65.309 mi
Registration #7	2011-08-18	79.377 mi
Registration #8	2012-07-28	91.809 mi
Registration #9	2012-07-31	91.809 mi
Registration #10	2013-08-09	104.918 mi
Registration #11	2013-08-14	104.918 mi
Registration #12	2014-07-23	116.298 mi
Registration #13	2015-07-22	129.764 mi
Registration #14	2016-06-20	151.277 mi
Registration #15	2017-06-20	151.277 mi
Registration #16	2018-06-20	151.277 mi
Registration #17	2019-06-20	151.277 mi
Registration #18	2020-06-20	151.277 mi
Registration #19	2021-06-20	151.277 mi
Registration #20	2022-06-20	151.277 mi
Registration #21	2023-06-20	151.277 mi
Registration #22	2024-06-20	151.277 mi
Registration #23	2025-06-20	151.277 mi
Registration #24	2026-06-20	151.277 mi
Registration #25	2027-06-20	151.277 mi
Registration #26	2028-06-20	151.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1990 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	1KD1037352