





report date: 2024-03-28

## General information

Make	MERCEDES-BENZ
Model	CL 500 CL500 BLUEEFFICIENCY
Colour	Silver
Year of manufacture	-
Top speed	155 mph
0 - 60 mph	4.9 seconds
Gearbox	7 speed automatic

## Engine & fuel consumption

Power	435 BHP
Max. torque	700 Nm at 1.800 rpm
Cylinders	8
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg



CarCheck.co.uk page 1/11



# Internet history

Entry	1

Lifety 1	
Date	2021-07-27
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



205763355855

#### **MOT** history

MOT #11	2021-02-03 09:10
MOT test number	841408698352

Result 

Next expiry date 

2022-02-11

**MOT #10** 2020-02-12 11:07

MOT test number 816076397027

**Result** ✓ Passed

MOT #9 2019-05-17 10:22

**MOT test number** 293911761582

Result \rightarrow Passed

**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #8 2018-05-24 15:57

Result \( \sqrt{Passed} \)

MOT #7 2017-05-06 10:24

**MOT test number** 520693834048

Advice Nearside Front Bonded suspension unit deteriorated but can function as intended (2.4.F.3)

Advice Engine cover fitted

**Advice** Offside Front Bonded suspension unit deteriorated but can function as intended (2.4.F.3)

**Advice** Under trays fitted

**MOT** test number

MOT #6 2016-06-24 11:27

MOT test number 107773253294

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 3/11



MOT #5 2016-06-22 10:21

**MOT test number** 785612104754

Result X Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #4 2016-05-20 14:01

MOT test number 100864936078

**Result** 
✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit 1.6mm (4.1.E.1)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Rear Tyre worn close to the legal limit 1.8mm (4.1.E.1)

MOT #3 2016-05-19 15:34

**MOT test number** 604887117839

Result X Failed

**Advice** Offside Rear Tyre worn close to the legal limit 1.8mm (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit 1.6mm (4.1.E.1)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2 2015-05-20 12:37

**MOT test number** 579900445171

Result \rightarrow Passed

CarCheck.co.uk page 4/11



MOT #1 2015-05-20 12:37

**MOT test number** 725390245135

Result X Failed

**Pass with rectification** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

**Pass with rectification** Front passenger door cannot be opened from inside the vehicle (6.2.B.1b)

CarCheck.co.uk page 5/11




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



# Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report <a href="https://example.com/here">here</a> .	
***************************************	
Plate changes	More info >
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-05-17
Last registration	2021-02-03
Complete history	See info



Registration #1	2012-05-17	7 mi
Registration #2	2015-05-20	39.936 mi
Registration #3	2016-05-19	54.065 mi
Registration #4	2016-05-20	54.065 mi
Registration #5	2016-06-22	54.488 mi
Registration #6	2016-06-24	54.493 mi
Registration #7		9.70 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



## Car features

60225	Air conditionin
60295	
0482	
0501	
0566	
0567	
0569	
iew the complete MERCEDES-BENZ factory list for this	More info >

# Dimensions & weight

Width	2130 mm
Height	1419 mm
Length	5095 mm
Wheel base	2955 mm
Kerb weight	2070 kg

# Additional information

Fuel tank capacity	83 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27892030024369

CarCheck.co.uk page 11/11