





report date: 2024-03-28

General information

| Make | MINI |
|---------------------|----------------|
| Model | COOPER D ONE D |
| Colour | Red |
| Year of manufacture | 2012 |
| Top speed | 114 mph |
| 0 - 60 mph | 11.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 90 BHP |
|-------------------------|---------------------|
| Max. torque | 215 Nm at 1.750 rpm |
| Engine capacity | 1.600 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 67.3 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-11-03

Pictures 14

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-12-29 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 9 |
| Failed MOT tests | 3 |
| Total advice items | 18 |
| Total items failed | 7 |

| MOT #12 | 2023-12-15 12:30 | |
|-------------------------------------------------------------------------------------------------------------------------------------|---------------------|--|
| MOT test number | 344435443802 | |
| Result | ✓ Passed | |
| Next expiry date | 2024-12-29 | |
| Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) | | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | | |
| Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened | d (1.1.14 (a) (ii)) | |

| MOT #11 | | 2022-12-30 10:31 |
|---------------------------|--------------------------------------------------------------------------------------------------|------------------------|
| MOT test | number | 671291323770 |
| Result | | ✓ Passed |
| Advice (4.1.4 (b)) | Front Headlamp has a product on the light source but not seriously reduc | ing light output both |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice | Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii)) | |
| Advice | Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Minor | Registration plate lamp inoperative in the case of multiple lamps or light so | ources (4.7.1 (b) (i)) |

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10 2022-12-30 10:31 **MOT** test number 581343220686 Result × Failed Pass with rectification Nearside Headlamp aim too low (4.1.2 (a)) **Advice** Front Headlamp has a product on the light source but not seriously reducing light output both (4.1.4 (b))Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) Pass with rectification Offside Headlamp aim too low (4.1.2 (a)) Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii)) Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice**

| MOT #9 | 2021-09-20 14:57 |
|-----------------------------------------------------------------------------------|------------------|
| MOT test number | 401639500422 |
| Result | ✓ Passed |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

MOT #8

MOT test number

892458087467

Result

Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

| MOT #7 | 2020-08-18 14:00 |
|-----------------|------------------|
| MOT test number | 994934801726 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6 2019-08-22 09:51

MOT test number 421667527868

MOT #5 2018-08-21 11:28

MOT test number 331494736150

Result ✓ Passed

MOT #4 2017-08-18 10:19

MOT test number 300514752155

Result
✓ Passed

Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

MOT #3 2016-08-16 07:53

MOT test number 312650280335

Advice Front tyres worn

Front tyres worn

Advice

MOT #2 2016-08-15 16:28

MOT test number 122036445067

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2015-07-29 12:41

MOT test number 378830415263

Notice Items removed from driver's view prior to test

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status

Days left

95

MOT expiry date

29 December 2024

Full MOT history

See MOT history

Tax calculation

| Vehicle class | 49 |
|-----------------------------------------|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report I | | e? |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----|
| | | |
| | | |
| | | |
| | | |
| ********* | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes See in this check if this MINI had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK NE | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2012-08-03 |
| Last registration | 2023-12-15 |
| Complete history | See info |



| Registration #1 | 2012-08-03 | 22 mi |
|------------------|------------|-----------|
| Registration #2 | 2015-07-29 | 26.954 mi |
| Registration #3 | 2016-08-15 | 35.621 mi |
| Registration #4 | 2016-08-16 | 35.632 mi |
| Registration #5 | 2017-08-18 | 44.256 mi |
| Registration #6 | 2018-08-21 | 53.760 mi |
| Registration #7 | 2019-08-22 | 63.547 mi |
| Registration #8 | | 71.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 71.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1683 mm |
|---------------------|---------|
| Height | 1407 mm |
| Length | 3723 mm |
| Wheel base | 2467 mm |
| Kerb weight | 1090 kg |
| Max. allowed weight | 1540 kg |

Additional information

| Fuel tank capacity | 40 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 4 page 12/1 |

Number of axles 2

Engine number 70678200