



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V
Colour	White
Year of manufacture	2012
Top speed	91 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	220 Nm at 1.250 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg






LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-13
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-19
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	14
Total items failed	5

MOT #13	2023-12-08 09:41
MOT test number	245499240746
Result	✓ Passed
Next expiry date	2024-12-19

MOT #12	2022-12-02 13:00
MOT test number	180273364284
Result	✓ Passed

MOT #11	2021-12-20 11:23
MOT test number	696382088710
Result	✓ Passed

MOT #10	2021-12-16 15:20
MOT test number	353513078980
Result	✗ Failed

Fail Offside Front Lower Suspension arm ball joint excessively worn O/S/F lower arm front bush has excessive movement (5.3.4 (a) (i))

MOT #9	2021-05-14 09:33
MOT test number	164202698132
Result	✓ Passed

**MOT #8**

2020-05-15 13:18

MOT test number

856577123000

Result

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Daytime running lamp not working
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7

2020-05-14 08:32

MOT test number

489129579620

Result

✗ Failed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Daytime running lamp not working
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources
(4.7.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6

2019-05-07 14:56

MOT test number

127524538603

Result

✓ Passed

**MOT #5** 2019-05-07 14:56**MOT test number** 582938932711**Result** ✗ Failed**Pass with rectification**

Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

MOT #4 2018-05-22 13:33**MOT test number** 617614530148**Result** ✓ Passed**Minor**

Nearside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #3 2017-05-06 10:59**MOT test number** 643105965562**Result** ✓ Passed**MOT #2** 2016-05-09 14:43**MOT test number** 156036709005**Result** ✓ Passed**MOT #1** 2015-05-22 10:39**MOT test number** 295062245146**Result** ✓ Passed**Advice**

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓
Taxed

Tax due:
1 December 2024

✓
MOT

Expires:
19 December 2024

Tax status		Valid until 1 December
Days left		215
MOT expiry date		19 December 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LF12ZWD
Plate since	2019-06-29
Current registration	 LF12ZWD
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-30
Last registration	2023-12-08
Complete history	See info



Registration #1	2012-05-30	11 mi
Registration #2	2015-05-22	28.237 mi
Registration #3	2016-05-09	35.588 mi
Registration #4	2017-05-06	47.530 mi
Registration #5	2018-05-22	64.064 mi
Registration #6	2019-05-07	75.589 mi
Registration #7	2019-05-07	75.589 mi
Registration #8	2020-05-14	88.373 mi
Registration #9	2020-05-14	88.373 mi
Registration #10	2020-05-14	88.373 mi
Registration #11	2020-05-14	88.373 mi
Registration #12	2020-05-14	88.373 mi
Registration #13	2020-05-14	88.373 mi
Registration #14	2020-05-14	88.373 mi
Registration #15	2020-05-14	88.373 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	1990 mm
Length	4892 mm
Wheel base	3000 mm
Kerb weight	1851 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3

Number of axles	2
Engine number	CAAA247921