



AK09WTY


report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	-
Top speed	125 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg






Internet history

Entry 1

Date	2021-11-25
Pictures	28
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #14	2023-01-10 16:12
MOT test number	986945970108
Result	✓ Passed
Next expiry date	2024-01-09

MOT #13	2023-01-09 10:04
MOT test number	876182518925
Result	✗ Failed
Advice	Rear Anti-roll bar linkage ball joint has slight play Both rear (5.3.4 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #12	2021-11-01 11:58
MOT test number	963940804993
Result	✓ Passed
Advice	Offside Outer Suspension component mounting prescribed area is corroded but not considered excessive body sill (5.3.6 (a) (i))
Advice	Nearside Outer Suspension component mounting prescribed area is corroded but not considered excessive body sill (5.3.6 (a) (i))

MOT #11	2021-10-19 16:09
MOT test number	282664676984
Result	✗ Failed

Fail Offside Rear Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

Advice Offside Outer Suspension component mounting prescribed area is corroded but not considered excessive body sill (5.3.6 (a) (i))

Fail Nearside Rear Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

Advice Nearside Outer Suspension component mounting prescribed area is corroded but not considered excessive body sill (5.3.6 (a) (i))

**MOT #10** 2020-11-13 15:25**MOT test number** 358912724982**Result** ✓ Passed

Advice Offside Outer Suspension component mounting prescribed area is corroded but not considered excessive body sill (5.3.6 (a) (i))

Advice Nearside Outer Suspension component mounting prescribed area is corroded but not considered excessive body sill (5.3.6 (a) (i))

MOT #9 2019-05-15 08:23**MOT test number** 243062492916**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm.worn on inside edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2-3mm (5.2.3 (e))

MOT #8 2018-05-04 13:13**MOT test number** 517216397162**Result** ✓ Passed

Advice Engine covers fitted

MOT #7 2018-05-04 12:52**MOT test number** 570961735885**Result** ✗ Failed

Fail Fuel system component insecure filter in engine bay (7.2.1)

Advice Engine covers fitted

MOT #6 2017-05-08 12:51**MOT test number** 362784621506**Result** ✓ Passed

**MOT #5** 2016-04-25 14:48**MOT test number** 189850956070**Result** ✓ Passed**Advice** Under tray fitted**Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn and slightly corroded (3.5.1i)**Advice** Engine bay covers fitted**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #4** 2015-04-27 11:57**MOT test number** 749937515112**Result** ✓ Passed**MOT #3** 2014-03-24 09:28**MOT test number** 605013384060**Result** ✓ Passed**MOT #2** 2013-03-18 09:34**MOT test number** 175127173499**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-03-23 09:29**MOT test number** 475783282013**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-25
Last registration	2023-01-10
Complete history	See info



Registration #1	2009-03-25	23 mi
Registration #2	2012-03-23	17.881 mi
Registration #3	2013-03-18	23.319 mi
Registration #4	2014-03-24	28.943 mi
Registration #5	2015-04-27	36.119 mi
Registration #6	2016-04-25	40.575 mi
Registration #7	2017-05-08	44.734 mi
Registration #8	2018-05-04	48.980 mi
Registration #9	2019-05-01	53.227 mi
Registration #10	2020-05-01	57.474 mi
Registration #11	2021-05-01	61.721 mi
Registration #12	2022-05-01	65.968 mi
Registration #13	2023-05-01	70.215 mi
Registration #14	2024-05-01	74.462 mi
Registration #15	2025-05-01	78.709 mi
Registration #16	2026-05-01	82.956 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1605 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	090622085755BG