



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Blue
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-30
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-12-11
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	49
Total items failed	6

MOT #192020-12-08 13:10

MOT test number442170591094

Result✓ Passed

Next expiry date2021-12-11

- AdviceNearside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceNearside Front Coil spring corroded (5.3.1 (b) (i))
- AdviceRear shocks absorbers starting to corrode front and rear suspension components starting to corrode
- AdviceNearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- AdviceOffside Rear condensation to rear lamp
- AdviceOffside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- AdviceOffside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceOffside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #18** 2020-12-08 11:35**MOT test number** 145522060669**Result** ✗ Failed**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Rear shocks absorbers starting to corrode front and rear suspension components starting to corrode**MAJOR** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear condensation to rear lamp**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #17** 2019-12-12 15:59**MOT test number** 280060282042**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2019-12-04 15:34**MOT test number** 614703820447**Result** ✗ Failed**MAJOR** Brake pedal has insufficient reserve travel (1.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



MOT #15 2018-12-05 15:18

MOT test number 495396558077

Result ✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Rear Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Offside Rear water in lamp
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14 2018-12-05 10:59

MOT test number 999872210041

Result ✗ Failed

- Minor** Offside Rear Obligatory mirror slightly damaged (3.3 (b) (i))
- MAJOR** Brake pedal has insufficient reserve travel excess brake pedal travel (1.1.2 (a))
- Advice** Offside Rear water in lamp
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Brake pedal has insufficient reserve travel (1.1.2 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #13**

2017-12-08 14:37

MOT test number

101554623764

Result

✓ Passed

- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Brake pipe slightly corroded front to rear. (3.6.B.2c)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Brake pipe slightly corroded front to rear. (3.6.B.2c)

MOT #12

2017-11-27 12:10

MOT test number

319896895981

Result

✗ Failed

- Fail** Offside front brake binding (3.7.B.1)
- Advice** Offside Brake pipe slightly corroded front to rear. (3.6.B.2c)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Fail** Brakes imbalanced across an axle (3.7.B.5b)
- Advice** Nearside Brake pipe slightly corroded front to rear. (3.6.B.2c)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Fail** Offside Stop lamp not working (1.2.1b)

MOT #11

2016-11-30 13:43

MOT test number

538708145188

Result

✓ Passed

MOT #10

2016-11-30 13:43

MOT test number

801643589912

Result

✗ Failed

- Pass with rectification** Nearside Front Headlamp aim too high (1.8)

**MOT #9** 2015-07-02 14:39**MOT test number** 445999914370**Result** ✓ Passed**MOT #8** 2015-07-02 11:14**MOT test number** 875642421997**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #7** 2014-07-02 09:40**MOT test number** 666553384189**Result** ✓ Passed**MOT #6** 2013-06-07 09:11**MOT test number** 999958253104**Result** ✓ Passed**MOT #5** 2013-06-07 09:11**MOT test number** 977198453106**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2012-06-06 13:00**MOT test number** 858418752198**Result** ✓ Passed



MOT #3	2011-06-06 13:08
MOT test number	775217751172
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2010-06-07 13:00
MOT test number	464738450119
Result	✓ Passed

MOT #1	2009-10-06 10:05
MOT test number	342069079468
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
20 March 2021

✕
MOT

Expired:
11 December 2021

Tax status	Expired at 20 March 2021
Days left	1137 days too late
MOT expiry date	11 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	WN56XGW
Plate since	2019-03-29
Current registration	WN56XGW
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-10-20
Last registration	2020-12-08
Complete history	See info



Registration #1	2006-10-20	25 mi
Registration #2	2009-10-06	25.284 mi
Registration #3	2010-06-07	27.582 mi
Registration #4	2011-06-06	32.047 mi
Registration #5	2012-06-06	36.913 mi
Registration #6	2013-06-07	39.492 mi
Registration #7	2014-07-02	43.030 mi
Registration #8	2015-07-02	46.823 mi
Registration #9	2015-07-02	46.823 mi
Registration #10	2016-11-30	49.707 mi
Registration #11	2016-11-30	50.000 mi
Registration #12	2016-11-30	50.000 mi
Registration #13	2016-11-30	50.000 mi
Registration #14	2016-11-30	50.000 mi
Registration #15	2016-11-30	50.000 mi
Registration #16	2016-11-30	50.000 mi
Registration #17	2016-11-30	50.000 mi
Registration #18	2016-11-30	50.000 mi
Registration #19	2016-11-30	50.000 mi
Registration #20	2016-11-30	50.000 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1250 kg
Max. allowed weight	1670 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU805903