



HGI3CKV

report date: 2024-03-28

General information

Make	MINI
Model	COOPER SD
Colour	Black
Year of manufacture	2013
Top speed	130 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-12-03
Pictures	11
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-15
Pictures	2
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-07-16
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	6
Total items failed	0
MOT #11	2023-07-17 16:42
MOT test number	764085960610
Result	✓ Passed
Next expiry date	2024-07-16
MOT #10	2022-06-16 08:18
MOT test number	385153243257
Result	✓ Passed
MOT #9	2022-04-05 15:20
MOT test number	160373949985
Result	✓ Passed
MOT #8	2021-07-15 13:41
MOT test number	595930562587
Result	✓ Passed

**MOT #7** 2021-05-07 15:08**MOT test number** 212839180341**Result** ✗ Failed

DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MAJOR Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))

MOT #6 2020-07-08 11:13**MOT test number** 727752724328**Result** ✓ Passed**MOT #5** 2019-06-17 10:22**MOT test number** 241107244474**Result** ✓ Passed**MOT #4** 2019-06-10 11:32**MOT test number** 178921594310**Result** ✗ Failed

MAJOR Nearside Front Road wheel badly distorted (5.2.2 (c) (i))

MOT #3 2018-06-22 11:45**MOT test number** 914679373098**Result** ✓ Passed**MOT #2** 2017-05-26 10:12**MOT test number** 235774641551**Result** ✓ Passed

Advice Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #1	2016-05-27 11:29
MOT test number	900083406260
Result	✓ Passed
Advice	Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
16 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	16 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-25
Last registration	2023-07-17
Complete history	See info



Registration #1	2013-06-25	12 mi
Registration #2	2016-05-27	22.224 mi
Registration #3	2017-05-26	29.718 mi
Registration #4	2018-06-22	34.944 mi
Registration #5	2019-06-10	38.246 mi
Registration #6	2019-06-17	38.362 mi
Registration #7	2020-07-08	42.847 mi
Registration #8	2020-06-20	45.277 mi
Registration #9	2020-06-20	45.277 mi
Registration #10	2020-06-20	45.277 mi
Registration #11	2020-06-20	45.277 mi
Registration #12	2020-06-20	45.277 mi
Registration #13	2020-06-20	45.277 mi
Registration #14	2020-06-20	45.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1150 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	70798418
---------------	----------