



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 CACHET
Colour	Black
Year of manufacture	2008
Top speed	105 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	143 g/km
CO2 label	F






Internet history

Entry 2



Date	2021-10-25
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-26
Pictures	8
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-16
MOT pass rate	52 %
MOT passed	13
Failed MOT tests	12
Total advice items	37
Total items failed	38

MOT #25	2023-09-04 14:55
MOT test number	110819001443
Result	✓ Passed
Next expiry date	2024-09-16
Advice	Nearside Front inner wing liner missing

MOT #24	2023-09-04 08:35
MOT test number	692444502624
Result	✗ Failed
Fail	Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front inner wing liner missing

MOT #23	2022-09-08 12:36
MOT test number	248443693401
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #22**

2022-09-05 09:50

MOT test number

839273731775

Result**✗ Failed****Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Exhaust system insecure (6.1.2 (a))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #21**

2021-09-13 11:44

MOT test number

553695624553

Result**✓ Passed****Advice** O/s front cv gater has small cut**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #20**

2021-09-13 11:44

MOT test number

415123705055

Result**✗ Failed****Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** O/s front cv gater has small cut**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #19** 2020-09-17 08:25**MOT test number** 228024764883**Result** ✓ Passed**MOT #18** 2020-09-15 14:42**MOT test number** 779395642426**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MOT #17** 2020-08-17 13:33**MOT test number** 218454624969**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Rear Service brake lagging in operation (1.2.1 (d))**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Rear Parking brake inoperative on one side does not meet reqd standard low reading (1.4.1 (a))**MOT #16** 2019-08-28 13:46**MOT test number** 688235238366**Result** ✓ Passed

**MOT #15** 2019-08-27 11:31**MOT test number** 396715041684**Result** ✗ Failed**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Headlamp aim too low (4.1.2 (a))**MOT #14** 2018-08-24 14:30**MOT test number** 483960614245**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Slight bind o/s/r brake**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear hand brake readings only just met requirements

**MOT #13**

2018-08-22 10:56

MOT test number

246533010776

Result**✗ Failed****Fail**

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Slight bind o/s/r brake

Fail

Spare wheel carrier insecure (6.1.5 (a))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Play in steering rack inner joint(s)

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Offside Rear hand brake readings only just met requirements

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Rear Exhaust system insecure back box wrap around clamp (6.1.2 (a))

MOT #12

2017-09-02 09:25

MOT test number

396143752323

Result**✓ Passed****Advice**

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #11** 2017-09-01 12:25**MOT test number** 119860051346**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Headlamp aim too low (1.8)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #10 2016-09-01 09:46**MOT test number** 753422808690**Result** ✓ Passed**MOT #9** 2016-08-31 10:29**MOT test number** 196616310261**Result** ✗ Failed

- Fail** Offside Headlamp aim too low (1.8)
- Fail** Nearside Rear rear brake binding (3.7.B.1)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)

MOT #8 2015-08-27 14:39**MOT test number** 639747950589**Result** ✓ Passed

**MOT #7** 2015-08-26 00:00**MOT test number** 720360361707**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Rear rear brake binding (3.7.B.1)**MOT #6** 2014-08-19 11:19**MOT test number** 479981534266**Result** ✓ Passed**Notice** Tyres worn front and rear**MOT #5** 2013-08-22 07:44**MOT test number** 726534033247**Result** ✓ Passed**MOT #4** 2013-08-21 14:56**MOT test number** 357703833210**Result** ✗ Failed**Fail** Steering wheel retaining device insecure (2.1.6)**MOT #3** 2012-08-28 15:37**MOT test number** 985541842291**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Wear in front antyroll bar bushes



MOT #2	2012-08-28 11:26
MOT test number	358671742438
Result	✗ Failed
Fail	Nearside Rear Tyre fouling a part of the vehicle (4.1.D.2)
Fail	Offside Front Front constant velocity joint is insecure (2.5.C.1b)
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Notice	Whear in front antyroll bar bushs

MOT #1	2011-05-21 11:26
MOT test number	129801041183
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
16 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	16 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2008-05-26
Last registration	2023-09-04
Complete history	See info



Registration #1	2008-05-26	20 mi
Registration #2	2011-05-21	27.748 mi
Registration #3	2012-08-28	41.390 mi
Registration #4	2012-08-28	41.390 mi
Registration #5	2013-08-21	49.201 mi
Registration #6	2013-08-22	49.201 mi
Registration #7	2014-08-19	55.551 mi
Registration #8	2015-08-26	64.609 mi
Registration #9	2015-08-27	64.613 mi
Registration #10	2016-08-31	75.094 mi
Registration #11	2016-09-01	75.096 mi
Registration #12	2017-09-01	82.242 mi
Registration #13	2017-09-02	82.244 mi
Registration #14	2018-08-22	87.410 mi
Registration #15	2018-08-22	87.410 mi
Registration #16	2018-08-22	87.410 mi
Registration #17	2018-08-22	87.410 mi
Registration #18	2018-08-22	87.410 mi
Registration #19	2018-08-22	87.410 mi
Registration #20	2018-08-22	87.410 mi
Registration #21	2018-08-22	87.410 mi
Registration #22	2018-08-22	87.410 mi
Registration #23	2018-08-22	87.410 mi
Registration #24	2018-08-22	87.410 mi
Registration #25	2018-08-22	87.410 mi
Registration #26	2018-08-22	87.410 mi

Registration #27	2020-05-20	20,000,000
Registration #28	2020-05-20	20,000,000

[More info >](#)



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1477 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	991 kg
Max. allowed weight	1362 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FST35836326