





**KRIIWNF**

report date: 2024-03-29

General information

Make	SUZUKI
Model	JIMNY SZ3
Colour	Black
Year of manufacture	2011
Top speed	87 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	110 Nm at 4.100 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-08-18
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #11 2023-08-09 10:26

MOT test number 808057498362

Result ✓ Passed

Next expiry date 2024-08-18

**Advice** General corrosion on vehicle underside, rear inner arches/inner sills, axles, brake pipes & fuel pipes (been previously coated in underseal).

MOT #10 2022-08-15 09:33

MOT test number 498852095183

Result ✓ Passed

MOT #9 2021-08-09 12:14

MOT test number 566806738807

Result ✓ Passed

**Advice** Slight corrosion underside & brake pipes (been coated in underseal). Front tyres slightly perished.

MOT #8 2020-08-08 11:53

MOT test number 777671848687

Result ✓ Passed

**Advice** Tyre worn close to legal limit/worn on edge All 4 (5.2.3 (e))

**MOT #7** 2020-08-05 15:11**MOT test number** 466182799509**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Tyre worn close to legal limit/worn on edge All 4 (5.2.3 (e))**MOT #6** 2019-08-06 15:35**MOT test number** 739102421348**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material to flexy (1.1.11 (c))**MOT #5** 2018-07-27 10:36**MOT test number** 809319729336**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #4** 2017-08-11 11:26**MOT test number** 230367024126**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #3	2016-07-26 15:08
MOT test number	623607069124
Result	✓ Passed
Advice	Advise front brake discs pitted
Advice	Advise o/s/f and n/s/f brake pipes pitted

MOT #2	2015-08-03 09:25
MOT test number	907805615292
Result	✓ Passed

MOT #1	2014-08-19 10:57
MOT test number	966911434238
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
18 August 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	18 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	KR11WNF
Plate since	2019-03-29
Current registration	KR11WNF
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-08-11
Last registration	2023-08-09
Complete history	<a href="#">See info</a>



Registration #1	2011-08-11	27 mi
Registration #2	2014-08-19	23.745 mi
Registration #3	2015-08-03	29.013 mi
Registration #4	2016-07-26	31.899 mi
Registration #5	2017-08-11	33.209 mi
Registration #6	2018-07-27	34.210 mi
Registration #7	2019-08-06	35.241 mi
Registration #8	2020-08-06	36.272 mi
Registration #9	2021-08-06	37.303 mi
Registration #10	2022-08-06	38.334 mi
Registration #11	2023-08-06	39.365 mi
Registration #12	2024-08-06	40.396 mi
Registration #13	2025-08-06	41.427 mi

More info >



Dimensions & weight

Width	1600 mm
Height	1705 mm
Length	3665 mm
Wheel base	2250 mm
Kerb weight	1135 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-2281719