





General information

Make	VAUXHALL
Model	CASCADA ELITE CDTI
Colour	Grey
Year of manufacture	2013
Top speed	132 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	165 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.956 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history	
Entry 1	
Date	2022-07-03
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-21
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #11	2023-07-20 14:57
MOT test number	296726650724
Result	✓ Passed
Next expiry date 2024-07-2	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #10		2023-07-20 12:56
MOT test	number	925972821858
Result		🗙 Failed
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))		
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources	(4.7.1 (b) (i))

МОТ #9	2022-07-22 13:19
MOT test number	282197654996
Result	✓ Passed





MOT #8	2021-08-26 13:43
MOT test number	126855521519
Result	✓ Passed
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
MOT #7	2020-08-26 12:48
MOT test number	195164063016
Result	✓ Passed
Advice Nearside Front Shock absorbers light misting of oil or has limite	ed damping effect (5.3.2 (b))
MOT #6	2019-08-29 11:44
MOT test number	422519398003
Result	✓ Passed
MOT #5	2019-03-22 13:57
MOT test number	893657503057
Result	✓ Passed
Advice N/s/r tyre getting low and stepping off on inner raised edge	
Advice Both rear coil springs slightly corroded	
MOT #4	2018-03-23 15:54

 MOT test number
 610956019827

 Result
 ✓ Passed

 Advice
 Nearside Front Tyre worn close to the legal limit (4.1.E.1)

 Advice
 Offside Front Tyre worn close to the legal limit (4.1.E.1)



BG13FXV
report date: 2024-03-28

МОТ #3	2018-03-23 12:46	
MOT test number	842269002175	
Result	🗙 Failed	
Fail Nearside Headlamp not working on dipped beam (1.7.5a)		
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		
Fail Nearside Headlamp not working on main beam (1.7.5a)		
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)		

MOT #2	2017-03-28 09:27
MOT test number	715764506540
Result	✓ Passed
Advice Items removed from driver's view prior to test	
MOT #1	2016-04-16 08:50
MOT #1 MOT test number	926564910251
	526561516251

Result

✓ Passed



Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expires: 21 July 2024	✓ МОТ
Tax status			Valid until 1 August
Days left			95
MOT expiry date			21 July 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

AND	

NUMBER OF CONTRACTOR OF CONTRA	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-04-29
Last registration	2023-07-20
Complete history	<u>See info</u>



Registration #1	2013-04-29	25 mi
Registration #2	2016-04-16	26.007 mi
Registration #3	2017-03-28	39.803 mi
Registration #4	2018-03-23	55.429 mi
Registration #5	2018-03-23	55.429 mi
Registration #6	2019-03-22	68.048 mi
Registration #7	2019-08-29	72.626 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi

More info >





Safety ratings

NCAP rating	****
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	<u>see crash video</u>



Dimensions & weight	
Width	2020 mm
Height	1443 mm
Length	4696 mm
Wheel base	2695 mm
Kerb weight	1741 kg
Max. allowed weight	2215 kg
Additional information	
Additional information Fuel tank capacity	56 l
	56 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 2