




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS 16V URBAN FOX
Colour	Black
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	124 Nm at 2.750 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-06
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-25
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	37
Total items failed	13

MOT #18 2023-09-26 09:13

MOT test number 473045893766

Result ✓ Passed

Next expiry date 2024-09-25

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17 2022-09-05 13:21

MOT test number 480504807312

Result ✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing both rear tyres cracking (5.2.3 (d) (ii))

MOT #16 2022-09-05 09:49

MOT test number 352792531872

Result ✗ Failed

- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing both rear tyres cracking (5.2.3 (d) (ii))



MOT #15 2021-09-02 16:32

MOT test number 714610224999

Result ✔ Passed

- Advice** Stone chips in windscreen.
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer sidewall. (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2021-08-21 12:30

MOT test number 690406687178

Result ✘ Failed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Stone chips in windscreen.
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer sidewall. (5.2.3 (d) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #13 2020-08-13 11:39

MOT test number 434559550538

Result ✔ Passed

- Advice** Front brake discs corroded
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords outer wall (cracking) (5.2.3 (d) (i))



MOT #12 2020-08-12 08:09

MOT test number 950596045230

Result ✗ Failed

- Fail** Nearside Front Road wheel fixing missing wheel bolt (5.2.1 (a) (i))
- Advice** Front brake discs corroded
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords outer wall (cracking) (5.2.3 (d) (i))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer wall (5.2.3 (d) (i))

MOT #11 2019-07-29 12:59

MOT test number 617951051580

Result ✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10 2018-08-03 08:51

MOT test number 164215073342

Result ✓ Passed

- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))



MOT #9	2017-07-18 12:20
MOT test number	212904099514
Result	✓ Passed
Advice	Offside Rear tyre outer wall cracking, no cords or ply showing.
Advice	Nearside Rear slight cut in near side rear tyre tread

MOT #8	2017-07-18 10:04
MOT test number	401525857272
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Rear tyre outer wall cracking, no cords or ply showing.

MOT #7	2016-07-18 10:15
MOT test number	880375606821
Result	✓ Passed
Advice	TPMS light is on
Advice	Offside Rear outer wall cracked
Advice	Nearside Rear cut in tread

MOT #6	2015-08-14 08:26
MOT test number	963123279215
Result	✓ Passed

MOT #5	2014-07-07 12:02
MOT test number	999878984186
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



MOT #4 2014-07-07 12:02

MOT test number 675898784103

Result ✗ Failed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Notice** Under-trays fitted obscuring some underside components

MOT #3 2013-06-24 12:52

MOT test number 588765673102

Result ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #2 2012-07-06 15:32

MOT test number 289758082490

Result ✓ Passed

MOT #1 2012-07-06 11:35

MOT test number 997638682101

Result ✗ Failed

- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
25 September 2024

Tax status Valid until 1 September

Days left 125

MOT expiry date 25 September 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-07-16
Last registration	2023-09-26
Complete history	See info



Registration #1	2009-07-16	24 mi
Registration #2	2012-07-06	18.000 mi
Registration #3	2012-07-06	18.000 mi
Registration #4	2013-06-24	19.082 mi
Registration #5	2014-07-07	20.131 mi
Registration #6	2015-08-14	22.861 mi
Registration #7	2016-07-18	25.210 mi
Registration #8	2017-07-18	27.026 mi
Registration #9	2017-07-18	27.026 mi
Registration #10	2018-08-03	30.357 mi
Registration #11	2019-09-26	31.377 mi
Registration #12	2019-09-26	31.377 mi
Registration #13	2019-09-26	31.377 mi
Registration #14	2019-09-26	31.377 mi
Registration #15	2019-09-26	31.377 mi
Registration #16	2019-09-26	31.377 mi
Registration #17	2019-09-26	31.377 mi
Registration #18	2019-09-26	31.377 mi
Registration #19	2019-09-26	31.377 mi

[More info >](#)



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1093 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BKR 035324