





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 R-LINE TDI BLUEMOTION TECHNOLOGY
Colour	Blue
Year of manufacture	2015
Top speed	140 mph
0 - 100 km/h	7.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	193 kW / 263 HP / 258 BHP
Max. torque	580 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-03

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-06
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	8
Total items failed	3

MOT #9	2023-07-06 12:29	
MOT test number	246397079085	
Result	✓ Passed	
Next expiry date 2024-0		
Minor Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))		

MOT #8	2023-07-05 12:57
MOT test number	893181873905
Result	X Failed
Fail Rear fog lamp not working (4.5.1 (a) (ii)) Minor Windscreen damaged but not adversely affecting driver's view Stone chip (3.	2 (a) (i))

MOT #7	2022-07-04 10:48
MOT test number	383241661660
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #6	2021-07-07 06:42
MOT test number	250964889036
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #4

Fail

Result

DG65OCL

report date: 2024-03-29

✓ Passed

MOT #5 2021-06-24 13:44 230305058307 **MOT** test number Result × Failed **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Offside Rear Outer Position lamp not working (4.2.1 (a) (ii)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

2020-10-07 15:06 **MOT** test number 959673774865 Result ✓ Passed **MOT** #3 2019-09-23 13:17

MOT test number 267418800642 Result ✓ Passed

MOT #2 2019-09-19 15:04

MOT test number 753977808080

Result × Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice

Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

MOT #1 2018-09-14 14:04 **MOT** test number 239011919856

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.


Damage 1

Date	
Category	
Туре	
Damage 2	
_	

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates. mber of plates. -More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-17
Last registration	2023-07-06
Complete history	See info



Registration #1	2015-09-17	19 mi
Registration #2	2018-09-14	16.984 mi
Registration #3	2019-09-19	23.077 mi
Registration #4	2019-09-23	23.077 mi
Registration #5	2020-10-07	27.761 mi
Registration #6	2021-06-24	30.180 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2208 mm
Height	1732 mm
Length	4889 mm
Wheel base	2893 mm
Kerb weight	2185 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	CVVA009582