



General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption


Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-06-25
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-12
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	21
Total items failed	15

MOT #14	2023-07-12 12:27
MOT test number	175927195662
Result	✓ Passed
Next expiry date	2024-07-12

MOT #13	2022-06-18 11:02
MOT test number	502583584132
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge TWO 235/65r17 (5.2.3 (e))
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Rear Tyre worn close to legal limit/worn on edge TWO replace soon (5.2.3 (e))

MOT #12	2022-06-18 11:02
MOT test number	344289468471
Result	✗ Failed
Advice	Rear Tyre worn close to legal limit/worn on edge TWO replace soon (5.2.3 (e))
Pass with rectification	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge TWO 235/65r17 (5.2.3 (e))
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #11** 2021-07-13 16:26**MOT test number** 779353874854**Result** ✓ Passed**MOT #10** 2021-07-13 09:51**MOT test number** 383162414680**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Upper Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #9** 2021-03-12 11:58**MOT test number** 577950389779**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside rear tyre wearing inner edge**Advice** Offside Rear Nail in tyre**Advice** Offside rear tyre wearing inner edge**MOT #8** 2020-03-13 11:49**MOT test number** 575508466657**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #7** 2019-03-15 10:39**MOT test number** 561606691488**Result** ✓ Passed

**MOT #6** 2019-03-12 14:42**MOT test number** 930243255368**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick BOTH SIDES (1.1.13 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Driver's view of the road through the swept area of the windscreen materially affected by an obstruction SUN VISOR WILL NOT STOW (3.1 (a) (ii))**MOT #5** 2018-09-26 17:16**MOT test number** 119160782744**Result** ✓ Passed**MOT #4** 2017-09-27 17:44**MOT test number** 977862675601**Result** ✓ Passed

**MOT #3** 2017-05-11 09:37**MOT test number** 832746585031**Result** ✓ Passed

- Advice** Engine cover/undertray fitted obscuring view
- Advice** Offside Rear Nail in tyre
- Advice** Deep cut in n/s/r tyre tread
- Advice** Front wiper blades starting to smear
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Exhaust rear section starting to corrode

MOT #2 2016-05-27 10:51**MOT test number** 413238215344**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1 2016-05-23 11:24**MOT test number** 741259769181**Result** ✗ Failed

- Fail** Offside Front Seat belt stitching badly frayed (5.2.2b)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
12 July 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-05-31
Last registration	2023-07-12
Complete history	See info



Registration #1	2013-05-31	15 mi
Registration #2	2016-05-23	24.605 mi
Registration #3	2016-05-27	24.788 mi
Registration #4	2017-05-11	32.846 mi
Registration #5	2017-09-27	36.358 mi
Registration #6	2018-09-26	42.468 mi
Registration #7	2019-03-12	45.796 mi
Registration #8	2019-03-15	45.799 mi
Registration #9	2019-05-20	45.799 mi
Registration #10	2019-05-20	45.799 mi
Registration #11	2019-05-20	45.799 mi
Registration #12	2019-05-20	45.799 mi
Registration #13	2019-05-20	45.799 mi
Registration #14	2019-05-20	45.799 mi
Registration #15	2019-05-20	45.799 mi
Registration #16	2019-05-20	45.799 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ