





report date: 2024-03-28

General information

| Make | VOLVO |
|---------------------|--------------------|
| Model | V40 T3 INSCRIPTION |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 130 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 150 BHP |
|-------------------------|---------------------|
| Max. torque | 250 Nm at 1.300 rpm |
| Engine capacity | 1.969 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 39.8 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/11



report date: 2024-03-28


Internet history

Entry 2

Date 2021-08-05


Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-08-05 |
|------|------------|
| D' I | 17 |

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-02-01 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 6 |
| Total items failed | 0 |

| MOT #4 | | 2024-01-24 09:19 |
|--|--|-----------------------------|
| MOT test | number | 876954473506 |
| Result | | ✓ Passed |
| Next exp | iry date | 2025-02-01 |
| Minor Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i)) | | |
| Advice (d) (i)) | Nearside Rear Tyre has a cut but not deep enough to reach the ply or o | cords Outer sidewall (5.2.3 |

| MOT #3 | 2023-01-27 12:39 |
|---|----------------------|
| MOT test number | 999326696195 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge Tyre measure | d at 2mm (5.2.3 (e)) |
| Minor Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface Reflector damaged. (4.8.1 (a) (i)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre measured at 2mm and worn inner edge. (5.2.3 (e)) | |
| Minor Obligatory mirror slightly damaged Central mirror damaged. (3.3 (b) (i)) | |

| MOT #2 | 2022-02-02 16:26 |
|-----------------|------------------|
| MOT test number | 416536211669 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2021-05-13 08:56

MOT test number 737516436828

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 277 |
| MOT expiry date | 1 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | Н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



HY180BV report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively. | |
|---|--------------|
| | |
| | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | NK NEW TOTAL |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



HY18OBV

report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-07-24 |
| Last registration | 2024-01-24 |
| Complete history | See info |



| Registration #1 | 2018-07-24 | 17 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-05-13 | 7.973 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 mi |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 60482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 98% |
| Children | 75% |
| Pedestrian | 88% |
| Safety systems | 100% |
| Overall rating | 92% |
| Video | see crash video |



Dimensions & weight

| Width | 1857 mm |
|---------------------|---------|
| Height | 1439 mm |
| Length | 4369 mm |
| Wheel base | 2647 mm |
| Kerb weight | 1393 kg |
| Max. allowed weight | 1965 kg |

Additional information

| Fuel tank capacity | 62 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/1 |

Number of axles 2

Engine number 2726996