



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D4 SE LUX
Colour	Black
Year of manufacture	2012
Top speed	134 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	142 g/km
CO2 label	F





Internet history

Entry 5

Date 2021-10-29

Pictures 51

Listing price [View report](#)



source: yesauto.com

Entry 4

Date 2021-10-21

Pictures 12

Listing price [View report](#)



source: cargurus.co.uk

Entry 3

Date 2021-10-21

Pictures 52

Listing price [View report](#)



source: autotrader.co.uk

Entry 2

Date 2021-07-12

Pictures

13

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date

2021-06-15

Pictures

13

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-23
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	23
Total items failed	1

MOT #12	2024-01-19 10:27
MOT test number	721170193652
Result	✓ Passed
Next expiry date	2025-01-23
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2023-01-24 12:24
MOT test number	705074024935
Result	✓ Passed
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10** 2023-01-18 16:55**MOT test number** 230749283118**Result** ✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged sidewall damage (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing bald on inner and outer edge (5.2.3 (d) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9 2022-01-19 10:34**MOT test number** 269837062117**Result** ✓ Passed**MOT #8** 2021-01-22 11:58**MOT test number** 777530593783**Result** ✓ Passed**MOT #7** 2020-01-09 13:39**MOT test number** 309478616646**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2019-01-15 10:51**MOT test number** 808629142679**Result** ✓ Passed**MOT #5** 2019-01-15 10:51**MOT test number** 730635414391**Result** ✗ Failed

Pass with rectification Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

MOT #4 2018-01-12 13:09**MOT test number** 904817319864**Result** ✓ Passed**MOT #3** 2017-01-14 12:51**MOT test number** 525009677494**Result** ✓ Passed

Advice Both front tyres have started to wear low on inner and outer edges

MOT #2 2016-01-19 14:05**MOT test number** 849070559467**Result** ✓ Passed

Advice Nearside Rear Seat belt not tested, child seat fitted

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front Pads low

MOT #1 2014-11-27 15:53**MOT test number** 619321134374**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
23 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-01-06
Last registration	2024-01-19
Complete history	See info



Registration #1	2012-01-06	17 mi
Registration #2	2014-11-27	29.068 mi
Registration #3	2016-01-19	39.041 mi
Registration #4	2017-01-14	46.822 mi
Registration #5	2018-01-12	56.489 mi
Registration #6	2019-01-15	74.372 mi
Registration #7	2019-01-15	74.372 mi
Registration #8	2020-01-09	87.755 mi
Registration #9	2021-01-22	97.403 mi
Registration #10	2022-01-22	97.403 mi
Registration #11	2022-01-22	97.403 mi
Registration #12	2022-01-22	97.403 mi
Registration #13	2022-01-22	97.403 mi
Registration #14	2022-01-22	97.403 mi
Registration #15	2022-01-22	97.403 mi
Registration #16	2022-01-22	97.403 mi
Registration #17	2022-01-22	97.403 mi
Registration #18	2022-01-22	97.403 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1628 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1208964
---------------	---------