



report date: 2024-03-28

General information

Make	MAZDA
Model	6 TS2
Colour	Grey
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	193 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-07-09
Pictures	14
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-01-21
Pictures	11
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-06-09
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	48
Total items failed	1

MOT #12	2023-06-06 10:10
MOT test number	277893666383
Result	✓ Passed
Next expiry date	2024-06-09
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement FRONT RADIUS ARM BUSH (5.3.4 (a) (i))
Advice	Rear Coil spring corroded BOTH SPRINGS (5.3.1 (b) (i))
Advice	Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11	2022-06-10 11:29
MOT test number	723370478014
Result	✓ Passed
MOT #10	2021-06-02 10:34
MOT test number	602156730266
Result	✓ Passed

**MOT #9**

2020-01-28 17:28

MOT test number

921520187294

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Slightly worn (1.1.14 (a) (ii))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Covers fitted stopping full inspection of outer sills (5.3.6 (a) (i))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge Inner shoulder worn castellated (5.2.3 (e))**Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear at rear slightly corroded (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material Slightly corroded (1.1.11 (c))**Advice** Exhaust corroded**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Slightly corroded and worn (1.1.14 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Covers fitted stopping full inspection of outer sills (5.3.6 (a) (i))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge Inner shoulder worn castellated (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))**Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear at rear slightly corroded (1.1.11 (c))**Advice** Fuel tank straps corroded**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #8**

2020-01-28 15:17

MOT test number

543976922995

Result**✗ Failed**

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Slightly worn (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Covers fitted stopping full inspection of outer sills (5.3.6 (a) (i))
- Advice** Exhaust corroded
- Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear at rear slightly corroded (1.1.11 (c))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge Inner shoulder worn castellated (5.2.3 (e))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Slightly corroded and worn (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Covers fitted stopping full inspection of outer sills (5.3.6 (a) (i))
- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear at rear slightly corroded (1.1.11 (c))
- Advice** Fuel tank straps corroded
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge Inner shoulder worn castellated (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material Slightly corroded (1.1.11 (c))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))

**MOT #7** 2019-02-16 12:46**MOT test number** 955227089463**Result** ✓ Passed

- Advice** Rear tyres worn on inner shoulders
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Advice** Nearside Rear brake caliper damp

MOT #6 2018-02-12 13:00**MOT test number** 316465908433**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Rear Offside and Nearside Tyres Worn slightly Unevenly on inner shoulders.
- Advice** Exhaust corroded at rear flanges

MOT #5 2017-02-09 10:15**MOT test number** 192124700394**Result** ✓ Passed

- Advice** Under trays covering some testable components
- Advice** Offside Front Outer Tyre worn close to the legal limit No Tread (4.1.E.1)
- Advice** Nearside Front Outer Tyre worn close to the legal limit No Tread (4.1.E.1)

MOT #4 2016-02-15 10:37**MOT test number** 839043285323**Result** ✓ Passed



MOT #3	2015-01-22 14:55
MOT test number	535682125063
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #2	2014-02-19 09:31
MOT test number	219200254032
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #1	2013-09-24 14:43
MOT test number	708647563237
Result	✓ Passed
Advice	Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 June 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-20
Current registration	*****
Plate since	2019-06-20

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-30
Last registration	2023-06-06
Complete history	See info



Registration #1	2010-09-30	10 mi
Registration #2	2013-09-24	27.251 mi
Registration #3	2014-02-19	32.300 mi
Registration #4	2015-01-22	40.718 mi
Registration #5	2016-02-15	49.716 mi
Registration #6	2017-02-09	57.417 mi
Registration #7	2018-02-12	65.038 mi
Registration #8	2019-02-16	73.226 mi
Registration #9	2020-02-16	81.414 mi
Registration #10	2021-02-16	89.602 mi
Registration #11	2022-02-16	97.790 mi
Registration #12	2023-02-16	105.978 mi
Registration #13	2024-02-16	114.166 mi
Registration #14	2025-02-16	122.354 mi
Registration #15	2026-02-16	130.542 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1435 kg
Max. allowed weight	1955 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 20316606