





report date: 2024-03-29

General information

Make	JAGUAR
Model	XF V6 LUXURY
Colour	Black
Year of manufacture	2012
Top speed	149 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	500 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	169 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-05-26	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/12



OV62LFX report date: 2024-03-29

MOT history

MOT expiry date	2025-03-08
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	9
Total items failed	5

MOT #13	2024-03-05 16:12
MOT test number	461136096051
Result	✓ Passed
Next expiry date	2025-03-08
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm front bush (5.3.4 (a) (i))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excertion front bush (5.3.4 (a) (i))	essive movement front arm

MOT #1	2	2024-03-05 09:58
MOT tes	t number	757442323382
Result		× Failed
Advice arm from	Nearside Front Suspension arm pin or bush worn but not resulting in excessive t bush (5.3.4 (a) (i))	e movement front
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm front bush (5.3.4 (a) (i))		movement front arm
Advice	Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail	Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	
	Rear Registration plate lamp does not illuminate simultaneously with the position (4.7.2 (a))	lamps (nearside and

CarCheck.co.uk page 3/12



OV62LFX report date: 2024-03-29

MOT #11

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #10	2022-01-31 16:45
MOT test number	390825959352
Result	✓ Passed
MOT #9	2021-07-16 15:02
MOT test number	609997461614
Result	✓ Passed
MOT #8	2020-12-19 10:56
MOT test number	430476430663
Result	✓ Passed
MOT #7	2019-07-09 14:12
MOT test number	697068413495
Result	✓ Passed
MOT #6	2018-12-11 16:49
MOT test number	649928470993
Result	✓ Passed

CarCheck.co.uk page 4/12



Result

OV62LFX

report date: 2024-03-29

Passed

MOT test number

Result

Pass with rectification

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (iii))

 MOT #4
 2017-12-15 12:06

 MOT test number
 278566339940

 Result
 ✓ Passed

 MOT #3
 2016-12-24 10:24

 MOT test number
 536310758660

MOT #2

MOT test number

440508899915

Result

Fail Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

 MOT #1
 2015-12-08 15:42

 MOT test number
 999543532449

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

OV62LFX

report date: 2024-03-29

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

More info >

More info >

CarCheck.co.uk page 9/12



OV62LFX report date: 2024-03-29

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



OV62LFX report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-12-31
Last registration	2024-03-05
Complete history	See info



Registration #1	2012-12-31	17 mi
Registration #2	2015-12-08	25.711 mi
Registration #3	2016-12-20	34.595 mi
Registration #4	2016-12-24	34.713 mi
Registration #5	2017-12-15	42.294 mi
Registration #6	2018-12-11	49.492 mi
Registration #7	2018-12-11	49.492 mi
Registration #8	2019-07-09	52.360 mi
Registration #9		
Registration #9		
Registration #10		0.074
		11.777 es
Registration #10		11.777 es 11.777 es
Registration #10 Registration #11		11.777 es 11.777 es 11.777 es
Registration #10 Registration #11 Registration #12		11.777 es 21.777 es 21.777 es
Registration #10 Registration #11 Registration #12 Registration #13		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es

More info >

page 11/12 CarCheck.co.uk



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	62%
Safety systems	71%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2053 mm
Height	1460 mm
Length	4961 mm
Wheel base	2909 mm
Kerb weight	1820 kg
Max. allowed weight	2360 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0595012306DT

CarCheck.co.uk page 12/12