



MEZI23I

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 TDI ALTITUDE
Colour	Silver
Year of manufacture	-
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	500 Nm at 1.750 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	19.3 mpg
Consumption extra urban	32.5 mpg
Consumption combined	25.9 mpg





Internet history

Entry 1

Date	2021-08-14
Pictures	38
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #10	2021-11-13 12:57
MOT test number	645283071187
Result	✓ Passed
Next expiry date	2022-11-19

MOT #9	2020-11-20 11:56
MOT test number	963245242379
Result	✓ Passed

- Minor

Rear reflector defective or damaged by up to 50% of the reflecting surface o/s and n/s (4.8.1 (a) (i))
- Advice

Front Brake hose slightly deteriorated o/s and n/s (1.1.12 (b) (ii))
- Advice

Nearside Front Fog light broken and not working
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Minor

Nearside Side repeater lens defective which has no effect on emitted light Damage (4.4.1 (b) (i))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #8	2020-11-18 13:21
MOT test number	937369771772
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Minor	Rear reflector defective or damaged by up to 50% of the reflecting surface o/s and n/s (4.8.1 (a) (i))
MAJOR	Offside Side repeater missing (4.4.1 (a) (ii))
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Front Brake hose slightly deteriorated o/s and n/s (1.1.12 (b) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Fog light broken and not working
Minor	Nearside Side repeater lens defective which has no effect on emitted light Damage (4.4.1 (b) (i))

MOT #7	2019-05-09 13:35
MOT test number	790906837881
Result	✓ Passed
Advice	Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #6** 2019-05-09 13:35**MOT test number** 270620995552**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #5** 2018-04-03 17:37**MOT test number** 386739229603**Result** ✓ Passed**MOT #4** 2017-04-08 12:12**MOT test number** 671842869564**Result** ✓ Passed**MOT #3** 2017-03-31 13:54**MOT test number** 540046353066**Result** ✗ Failed**Fail** Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Side repeater excessively deteriorated so that it is not visible from a reasonable distance (1.4.A.2e)**Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear Stop lamp not working (1.2.1b)



MOT #2	2016-04-01 12:40
MOT test number	192246807607
Result	✓ Passed

MOT #1	2016-02-13 10:38
MOT test number	459264995285
Result	✗ Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2007-02-23
Last registration	2021-11-13
Complete history	See info



Registration #1	2007-02-23	14 mi
Registration #2	2016-02-13	88.758 mi
Registration #3	2016-04-01	88.771 mi
Registration #4	2017-03-31	97.967 mi
Registration #5	2017-04-08	98.105 mi
Registration #6	2018-04-03	107.843 mi
Registration #7	2019-05-20	117.577 mi
Registration #8	2019-05-20	117.577 mi
Registration #9	2019-05-20	117.577 mi
Registration #10	2019-05-20	117.577 mi
Registration #11	2019-05-20	117.577 mi
Registration #12	2019-05-20	117.577 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2530 kg
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKS 042861