



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO VVTI T SPIRIT
Colour	Silver
Year of manufacture	2006
Top speed	115 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	170 Nm at 4.800 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-12-13
Pictures	11
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-12-11
Pictures	33
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-13
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	22
Total items failed	17

MOT #22 2023-11-28 13:48

MOT test number 586016343923

Result ✓ Passed

Next expiry date 2024-12-13

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #21 2022-11-15 15:09

MOT test number 400843656459

Result ✓ Passed

MOT #20 2022-11-15 15:09

MOT test number 550685147878

Result ✗ Failed

Pass with rectification Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #19** 2021-12-14 19:23**MOT test number** 821436284442**Result** ✓ Passed**MOT #18** 2020-11-26 12:35**MOT test number** 949981188186**Result** ✓ Passed**MOT #17** 2020-11-24 15:34**MOT test number** 502528862750**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #16** 2019-10-30 14:40**MOT test number** 457139134944**Result** ✓ Passed**MOT #15** 2018-10-28 13:57**MOT test number** 724136218657**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge cracked and perished (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge cracked and perished (5.2.3 (e))**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #14**

2017-10-28 12:20

MOT test number

666867695157

Result

✓ Passed

Advice Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

Advice Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

MOT #13

2017-10-28 10:53

MOT test number

916772178525

Result

✗ Failed

Advice Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

Advice Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

Advice Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Fail Offside Front Wheel nut(s) missing (4.2.A.1e)

Fail Nearside Headlamp insecure (1.7.3)

MOT #12

2016-10-29 14:44

MOT test number

420383645364

Result

✓ Passed

MOT #11

2015-10-31 15:00

MOT test number

160613107467

Result

✓ Passed

**MOT #10** 2015-10-31 12:32**MOT test number** 402973658284**Result** ✗ Failed**Fail** Offside Rear Inner Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Headlamp aim too high (1.8)**Fail** Nearside Front Headlamp aim too low (1.8)**MOT #9** 2014-09-27 13:04**MOT test number** 547590574268**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-09-27 11:13**MOT test number** 325160174481**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #7** 2013-10-27 12:28**MOT test number** 978370103376**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2013-10-27 12:28**MOT test number** 527210603385**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low and too far to the right. (1.8)**Pass with rectification** Nearside Headlamp aim too low and too far to the right. (1.8)**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-10-27 13:31**MOT test number** 938111602351**Result** ✓ Passed**MOT #4** 2011-10-29 11:13**MOT test number** 428732001317**Result** ✓ Passed**Notice** Nearside and offside rear tyres worn down to 2mm**MOT #3** 2010-10-25 15:33**MOT test number** 511138490299**Result** ✓ Passed**MOT #2** 2010-10-25 15:33**MOT test number** 770158790239**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2009-04-29 12:19**MOT test number** 491759619139**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
13 December 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-07-31
Last registration	2023-11-28
Complete history	See info



Registration #1	2006-07-31	28 mi
Registration #2	2009-04-29	22.432 mi
Registration #3	2010-10-25	36.460 mi
Registration #4	2011-10-29	44.719 mi
Registration #5	2012-10-27	54.558 mi
Registration #6	2013-10-27	63.606 mi
Registration #7	2014-09-27	71.498 mi
Registration #8	2014-09-27	71.498 mi
Registration #9	2015-10-31	79.415 mi
Registration #10	2015-10-31	79.432 mi
Registration #11	2016-10-29	85.185 mi
Registration #12	2017-10-28	90.447 mi
Registration #13	2018-10-28	95.217 mi
Registration #14	2019-10-28	95.217 mi
Registration #15	2020-10-28	95.217 mi
Registration #16	2021-10-28	95.217 mi
Registration #17	2022-10-28	95.217 mi
Registration #18	2023-10-28	95.217 mi
Registration #19	2023-10-28	95.217 mi
Registration #20	2023-10-28	95.217 mi
Registration #21	2023-10-28	95.217 mi
Registration #22	2023-10-28	95.217 mi
Registration #23	2023-10-28	95.217 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1ZZE466915