



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 230 KOMPRESSOR
Colour	Silver
Year of manufacture	2003
Top speed	149 mph
0 - 60 mph	7.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	279 Nm at 2.500 rpm
Engine capacity	2.295 cc
Cylinders	4
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	39.8 mpg
Consumption combined	28.8 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-07-26
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-17
MOT pass rate	82 %
MOT passed	18
Failed MOT tests	4
Total advice items	16
Total items failed	4

MOT #22	2024-03-13 12:46
MOT test number	635072704268
Result	✓ Passed
Next expiry date	2025-03-17
Advice	Central Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #21	2023-03-09 14:46
MOT test number	910688734666
Result	✓ Passed
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Advice	Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #20	2022-03-04 10:28
MOT test number	411257491192
Result	✓ Passed
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Advice	Rear Tyre worn close to legal limit/worn on edge from edges (5.2.3 (e))

MOT #19	2021-03-18 09:12
MOT test number	606956417651
Result	✓ Passed

**MOT #18** 2020-02-03 11:01**MOT test number** 458723337194**Result** ✓ Passed**MOT #17** 2018-06-11 18:16**MOT test number** 142684162549**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16 2017-06-16 13:37**MOT test number** 615020645876**Result** ✓ Passed**MOT #15** 2017-06-16 09:35**MOT test number** 493631771694**Result** ✗ Failed

- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Advice** Nearside Front headlight full of condensation but beam pattern o k at test time

MOT #14 2016-05-14 07:30**MOT test number** 798081471883**Result** ✓ Passed

**MOT #13** 2016-05-12 14:55**MOT test number** 823372604216**Result** ✗ Failed**Fail** Offside Rear Brake pipe leaking (3.6.A.1)**MOT #12** 2015-07-08 10:19**MOT test number** 159149185115**Result** ✓ Passed**MOT #11** 2014-06-25 09:34**MOT test number** 766026674167**Result** ✓ Passed**MOT #10** 2013-07-09 10:06**MOT test number** 697740493186**Result** ✓ Passed**MOT #9** 2013-07-09 10:06**MOT test number** 826780193150**Result** ✗ Failed**Pass with rectification** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)**MOT #8** 2012-06-28 12:41**MOT test number** 838860182110**Result** ✓ Passed**MOT #7** 2011-07-19 12:14**MOT test number** 935730701241**Result** ✓ Passed**Notice** Nail in offside front tyre

**MOT #6** 2011-07-19 11:14**MOT test number** 346090001227**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Nail in offside front tyre**MOT #5** 2010-07-19 09:18**MOT test number** 530960900273**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-07-20 14:47**MOT test number** 213731309232**Result** ✓ Passed**MOT #3** 2008-07-22 12:03**MOT test number** 223144308225**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #2** 2007-07-20 12:58**MOT test number** 474401007229**Result** ✓ Passed**MOT #1** 2006-07-20 09:16**MOT test number** 552041906266**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
17 March 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	17 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	YK03GRH
Plate since	2019-03-28
Current registration	YK03GRH
Plate since	2019-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-07-23
Last registration	2024-03-13
Complete history	See info



Registration #1	2003-07-23	15 mi
Registration #2	2006-07-20	13.381 mi
Registration #3	2007-07-20	19.366 mi
Registration #4	2008-07-22	26.441 mi
Registration #5	2009-07-20	33.370 mi
Registration #6	2010-07-19	39.108 mi
Registration #7	2011-07-19	47.558 mi
Registration #8	2011-07-19	47.558 mi
Registration #9	2012-06-28	53.824 mi
Registration #10	2013-07-09	64.100 mi
Registration #11	2014-06-25	68.047 mi
Registration #12	2015-07-08	71.725 mi
Registration #13	2016-07-08	75.000 mi
Registration #14	2017-07-08	78.000 mi
Registration #15	2018-07-08	81.000 mi
Registration #16	2019-07-08	84.000 mi
Registration #17	2020-07-08	87.000 mi
Registration #18	2021-07-08	90.000 mi
Registration #19	2022-07-08	93.000 mi
Registration #20	2023-07-08	96.000 mi
Registration #21	2024-03-13	99.000 mi
Registration #22		
Registration #23		

More info >



Dimensions & weight

Width	1715 mm
Height	1281 mm
Length	4010 mm
Wheel base	2400 mm

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11198332474586