



report date: 2024-03-29

General information

Make	FORD
Model	B-MAX ZETEC
Colour	White
Year of manufacture	2014
Top speed	109 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 99 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-07-30
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-29
Pictures	22
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-27
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	7
Total items failed	2

MOT #9	2023-06-19 12:54
MOT test number	455583708797
Result	✓ Passed
Next expiry date	2024-06-27

MOT #8	2022-06-28 11:27
MOT test number	280759516627
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #7	2021-06-08 10:02
MOT test number	872334535611
Result	✓ Passed
Minor	Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #6	2021-06-07 11:06
MOT test number	819865675724
Result	✗ Failed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing tread area (5.2.3 (d) (ii))
Fail	Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))
Minor	Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #5** 2020-06-16 09:17**MOT test number** 477507784083**Result** ✓ Passed**MOT #4** 2019-05-31 12:23**MOT test number** 594421109344**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**MOT #3** 2019-05-25 09:03**MOT test number** 224680533454**Result** ✗ Failed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #2** 2018-06-01 14:38**MOT test number** 591591255949**Result** ✓ Passed**Advice** Both rear tyres punctured**MOT #1** 2017-06-06 13:57**MOT test number** 379083837800**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
27 June 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	27 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-02
Last registration	2023-06-19
Complete history	See info



Registration #1	2014-09-02	7 mi
Registration #2	2017-06-06	18.258 mi
Registration #3	2018-06-01	23.806 mi
Registration #4	2019-05-25	28.856 mi
Registration #5	2019-05-31	28.906 mi
Registration #6	2020-06-16	33.478 mi
Registration #7	2020-06-16	33.478 mi
Registration #8	2020-06-16	33.478 mi
Registration #9	2020-06-16	33.478 mi
Registration #10	2020-06-16	33.478 mi
Registration #11	2020-06-16	33.478 mi
Registration #12	2020-06-16	33.478 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	ES23713