



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 SX
Colour	Blue
Year of manufacture	-
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg





Internet history

Entry 1

Date	2021-07-15
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #19 2022-08-23 12:23

MOT test number 809375429148

Result ✓ Passed

Next expiry date 2023-08-22

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Repair to outer sills
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Headlamp aim adjusted
- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #18**

2022-08-18 12:51

MOT test number

232611623077

Result**✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**MAJOR** Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced Outersill (7.1.1 (a) (i))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))**MAJOR** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**MAJOR** Offside Seat belt anchorage prescribed area strength or continuity significantly reduced Outersill (7.1.1 (a) (i))**Advice** Offside Rear Tyre out of shape**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #17**

2021-08-19 12:49

MOT test number

112567248482

Result**✓ Passed**



MOT #16		2021-08-17 12:59
MOT test number		336166800586
Result		✗ Failed
MAJOR	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
MAJOR	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice	Nearside Rear Inner Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii))	
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #15		2020-07-06 09:30
MOT test number		793960979515
Result		✓ Passed
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge cracking (5.2.3 (e))	
Minor	Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14		2019-07-16 08:23
MOT test number		870000934609
Result		✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Exhaust has a minor leak of exhaust gases joint (6.1.2 (a))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))	

**MOT #13** 2018-07-26 09:24**MOT test number** 569251473574**Result** ✓ Passed**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened OS +NS (1.1.14 (a) (ii))**MOT #12** 2017-07-31 12:57**MOT test number** 449382735702**Result** ✓ Passed**MOT #11** 2016-11-05 11:51**MOT test number** 199436016782**Result** ✓ Passed**MOT #10** 2016-10-29 11:04**MOT test number** 992439357283**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #9** 2015-10-30 12:53**MOT test number** 263031248375**Result** ✓ Passed

**MOT #8** 2015-10-12 08:45**MOT test number** 115815496486**Result** ✗ Failed

- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Direction indicators incorrect colour (1.4.A.2f)
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall (4.1.D.1a)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #7 2013-09-12 14:06**MOT test number** 359165653212**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2012-09-19 15:15**MOT test number** 319713462404**Result** ✓ Passed

- Advice** Direction indicators slightly discoloured (1.4.A.2f)
- Notice** Rear exhaust box corroded.

MOT #5 2011-09-13 15:33**MOT test number** 248886751254**Result** ✓ Passed

- Notice** Both nearside tyres sidewall scrubbed.
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)

**MOT #4** 2010-09-14 13:51**MOT test number** 684047350283**Result** ✓ Passed**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** Nearside front tyre sidewall slightly scrubbed**MOT #3** 2009-08-29 13:41**MOT test number** 630811449275**Result** ✓ Passed**MOT #2** 2008-09-13 11:34**MOT test number** 974397258275**Result** ✓ Passed**MOT #1** 2007-09-18 15:07**MOT test number** 304051067255**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-09-19
Last registration	2022-08-23
Complete history	See info



Registration #1	2004-09-19	8 mi
Registration #2	2007-09-18	23.428 mi
Registration #3	2008-09-13	27.014 mi
Registration #4	2009-08-29	30.608 mi
Registration #5	2010-09-14	34.585 mi
Registration #6	2011-09-13	38.714 mi
Registration #7	2012-09-19	43.190 mi
Registration #8	2013-09-12	46.924 mi
Registration #9	2015-10-12	50.813 mi
Registration #10	2015-10-30	50.841 mi
Registration #11	2016-10-29	59.223 mi
Registration #12	2019-08-23	59.223 mi
Registration #13	2019-08-23	59.223 mi
Registration #14	2019-08-23	59.223 mi
Registration #15	2019-08-23	59.223 mi
Registration #16	2019-08-23	59.223 mi
Registration #17	2019-08-23	59.223 mi
Registration #18	2019-08-23	59.223 mi
Registration #19	2019-08-23	59.223 mi
Registration #20	2019-08-23	59.223 mi
Registration #21	2019-08-23	59.223 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1654 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	932 kg
Max. allowed weight	1340 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7P4574860