



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA EXCLUSIV CDTI 8V
Colour	Black
Year of manufacture	2008
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-24
Pictures	25
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-10-31
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	29
Total items failed	28

MOT #20	2022-10-28 14:34
MOT test number	436963813537
Result	✓ Passed
Next expiry date	2023-10-31
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #19**

2022-10-28 09:32

MOT test number

635200263368

Result**✗ Failed**

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Hydraulic brake calliper insecurely mounted (1.1.16 (c) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #18

2021-10-02 09:12

MOT test number

276010909262

Result**✓ Passed**

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2021-10-01 12:26

MOT test number

572742802388

Result**✗ Failed****Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #16**

2020-10-31 13:20

MOT test number

198019633976

Result**✓ Passed****Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Suspension component mounting prescribed area is corroded but not considered excessive Light surface corrosion to rear inner sills. Outer sill covers and rear inner wheel arch liners fitted. (5.3.6 (a) (i))

**MOT #15**

2020-10-28 17:28

MOT test number

636909190777

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge ON LIMIT. ADVISE REPLACEMENT NOW (5.2.3 (e))

Fail Offside Brake pipe excessively corroded Front to rear. Corroded/weakened (1.1.11 (c))

Advice Suspension component mounting prescribed area is corroded but not considered excessive Light surface corrosion to rear inner sills. Outer sill covers and rear inner wheel arch liners fitted. (5.3.6 (a) (i))

Fail Nearside Rear Suspension arm pin or bush excessively worn Trailing arm, front bush. (5.3.4 (a) (i))

Advice Brake pipe corroded, covered in grease or other material Nearside front to rear pipe heavily corroded/pitted above fuel tank. ADVISE REPLACEMENT SOON. (1.1.11 (c))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Brake pipe excessively corroded Front to rear. Corroded/weakened (1.1.11 (c))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Rear Suspension arm pin or bush excessively worn Trailing arm, front bush. (5.3.4 (a) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material Pipe inside wheel arch corroded (1.1.11 (c))

MOT #14

2019-10-07 13:44

MOT test number

742256704335

Result

✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material rear feeds x 2 (1.1.11 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2019-10-07 09:58**MOT test number** 837661528200**Result** ✗ Failed**Fail** Offside Windscreen washer not working (3.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Windscreen washer not working (3.5 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material rear feeds x 2 (1.1.11 (c))**MOT #12** 2018-10-20 10:42**MOT test number** 815349666420**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material corroded near fuel tank (1.1.11 (c))**MOT #11** 2018-10-20 08:12**MOT test number** 489602261277**Result** ✗ Failed**Advice** Rear Brake pipe corroded, covered in grease or other material corroded near fuel tank (1.1.11 (c))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MOT #10** 2017-10-27 11:32**MOT test number** 302772783416**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2017-10-27 08:27**MOT test number** 617980575677**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #8** 2016-10-26 09:19**MOT test number** 714375098196**Result** ✓ Passed**MOT #7** 2015-10-28 10:55**MOT test number** 976267133811**Result** ✓ Passed**MOT #6** 2014-10-06 14:36**MOT test number** 335979974255**Result** ✓ Passed**MOT #5** 2014-10-02 11:14**MOT test number** 358445274422**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #4** 2013-10-30 10:21**MOT test number** 765203303359**Result** ✓ Passed



MOT #3	2012-10-25 11:21
MOT test number	368619392425
Result	✓ Passed
MOT #2	2011-10-27 15:00
MOT test number	725740901380
Result	✓ Passed
MOT #1	2011-10-26 11:41
MOT test number	468769791298
Result	✗ Failed
Fail	Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)



Tax & MOT check

X

Untaxed

Tax expired:
2 October 2023

X

MOT

Expired:
31 October 2023

Tax status	Expired at 2 October 2023
Days left	211 days too late
MOT expiry date	31 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	VAUXH
Plate since	2024-03-29
Current registration	VAUXH
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-10-31
Last registration	2022-10-28
Complete history	See info



Registration #1	2008-10-31	10 mi
Registration #2	2011-10-26	23.749 mi
Registration #3	2011-10-27	23.779 mi
Registration #4	2012-10-25	31.087 mi
Registration #5	2013-10-30	38.196 mi
Registration #6	2014-10-02	45.677 mi
Registration #7	2014-10-06	45.759 mi
Registration #8	2015-10-28	51.658 mi
Registration #9	2016-10-26	59.143 mi
Registration #10	2017-10-27	63.572 mi
Registration #11	2017-10-27	63.572 mi
Registration #12	2019-10-28	75.277 mi
Registration #13	2019-10-28	75.277 mi
Registration #14	2019-10-28	75.277 mi
Registration #15	2019-10-28	75.277 mi
Registration #16	2019-10-28	75.277 mi
Registration #17	2019-10-28	75.277 mi
Registration #18	2019-10-28	75.277 mi
Registration #19	2019-10-28	75.277 mi
Registration #20	2019-10-28	75.277 mi
Registration #21	2019-10-28	75.277 mi
Registration #22	2019-10-28	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1428 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	5945562