



report date: 2024-03-28

General information

Make	KIA
Model	RIO DOMINO
Colour	Silver
Year of manufacture	2011
Top speed	108 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





## MOT history

MOT expiry date	2024-10-20
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	22
Total items failed	0

MOT #10 2023-10-21 10:36

MOT test number 522283529710

Result ✓ Passed

Next expiry date 2024-10-20

- Minor** Offside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Central Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Outer Vehicle structure is deformed but structural rigidity is not significantly reduced sill (6.1.1 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear axle corroded
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))
- Advice** Brake pipe corroded, covered in grease or other material both main (1.1.11 (c))
- Advice** Direction indicator slightly discoloured all (4.4.3 (a))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #9** 2022-08-15 09:07**MOT test number** 298674356523**Result** ✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Radiator supports and subframe corroded

**MOT #8** 2021-08-17 09:05**MOT test number** 166502280929**Result** ✓ Passed**MOT #7** 2020-07-03 10:53**MOT test number** 106976415197**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2019-05-29 11:29**MOT test number** 226976640282**Result** ✓ Passed**MOT #5** 2018-06-15 10:34**MOT test number** 352680666347**Result** ✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #4	2017-06-06 11:20
MOT test number	585034361276
Result	✓ Passed
MOT #3	2016-06-10 11:32
MOT test number	466689297481
Result	✓ Passed
MOT #2	2015-06-10 11:39
MOT test number	799701865114
Result	✓ Passed
MOT #1	2014-06-03 11:30
MOT test number	546104554189
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
20 October 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	20 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2011-06-17
Last registration	2023-10-21
Complete history	<a href="#">See info</a>



Registration #1	2011-06-17	13 mi
Registration #2	2014-06-03	13.660 mi
Registration #3	2015-06-10	18.629 mi
Registration #4	2016-06-10	21.839 mi
Registration #5	2017-06-06	25.746 mi
Registration #6	2018-06-15	37.980 mi
Registration #7	2019-06-06	38.377 mi
Registration #8	2020-06-06	38.377 mi
Registration #9	2021-06-06	38.377 mi
Registration #10	2022-06-06	38.377 mi
Registration #11	2023-10-21	38.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1244 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4EEAH382395