



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	HILUX INVINCIBLE 4X4 D-4D DCB
Colour	Black
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	343 Nm at 3.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	36.7 mpg
CO2 emission	203 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-05-17
Pictures	20
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-26
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	11
Total items failed	1

## MOT #10 2023-10-27 09:26

MOT test number 851808296515

Result ✓ Passed

Next expiry date 2024-10-26

**Advice** CARRIED OUT VEHICLE INSPECTION UNDER WET CONDITIONS.**Advice** Engine cover & under body cover panels fitted obscuring some testable components.

## MOT #9 2022-10-24 09:20

MOT test number 854013837544

Result ✓ Passed

## MOT #8 2022-03-15 08:45

MOT test number 407232640626

Result ✓ Passed**Advice** General corrosion underneath vehicle chassis rails outriggers body mounts

## MOT #7 2022-03-14 14:00

MOT test number 643398335154

Result ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** General corrosion underneath vehicle chassis rails outriggers body mounts

**MOT #6** 2021-04-06 15:44**MOT test number** 231632811564**Result** ✓ Passed**Advice** General corrosion on chassis rails out riggers**MOT #5** 2021-04-01 15:48**MOT test number** 221210634502**Result** ✗ Failed**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** General corrosion on chassis rails out riggers**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #4** 2020-03-16 16:16**MOT test number** 996422432076**Result** ✓ Passed**Advice** General corrosion on chassis rails outriggers rear springs**MOT #3** 2020-03-16 16:16**MOT test number** 989374278627**Result** ✗ Failed**Pass with rectification** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**Advice** General corrosion on chassis rails outriggers rear springs**MOT #2** 2019-04-01 16:26**MOT test number** 572860640592**Result** ✓ Passed



MOT #1	2018-03-21 11:53
MOT test number	962003275301
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
26 October 2024

Tax status		Valid until 1 November
Days left		185
MOT expiry date		26 October 2024
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	 KM15BFX
Plate since	2019-03-29
Current registration	 KM15BFX
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-04-01
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2015-04-01	20 mi
Registration #2	2018-03-21	21.208 mi
Registration #3	2019-04-01	30.195 mi
Registration #4	2020-03-16	34.610 mi
Registration #5	2020-03-16	34.610 mi
Registration #6	2021-04-01	39.866 mi
Registration #7	2023-10-27	39.866 mi
Registration #8	2023-10-27	39.866 mi
Registration #9	2023-10-27	39.866 mi
Registration #10	2023-10-27	39.866 mi
Registration #11	2023-10-27	39.866 mi
Registration #12	2023-10-27	39.866 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1835 mm
Height	1860 mm
Length	5260 mm
Kerb weight	2135 kg
Max. allowed weight	3080 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1KDA716182