





report date: 2024-03-29

## General information

Make	PEUGEOT
Model	508 HDI CC ALLURE
Colour	White
Year of manufacture	2012
Top speed	126 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/14



# Internet history

## Entry 1

Date 2022-01-03

Pictures 64

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



# MOT history

MOT expiry date	2025-03-15
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	32
Total items failed	5

MOT #19		2024-03-07 11:34
MOT test	number	819703185741
Result		✓ Passed
Next expi	ry date	2025-03-15
Advice	Rear Tyre worn close to legal limit/worn on edge Both rear at limit 1.6mm (5.2.3	3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #18	2023-03-16 11:15
MOT test number	568039690769
Result	✓ Passed

MOT #17		2023-03-10 14:58
MOT test	number	254541298509
Result		<b>X</b> Failed
MAJOR	Offside Rear Road wheel fixing missing (5.2.1 (a) (i))	
MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))		
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

CarCheck.co.uk page 3/14



MOT #16 2022-03-02 17:41

**MOT test number** 577362592552

Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #15** 2021-03-06 11:40

MOT test number 671543216904

Result \( \sqrt{Passed} \)

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2021-03-06 11:40

**MOT test number** 259222973629

Result X Failed

**Pass with rectification** Nearside Headlamp aim too far to the left (4.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

MOT #13 2020-03-12 11:26

**MOT test number** 674935147046

Result Passed

**Advice** Front Direction indicator slightly discoloured Both sides (4.4.3 (a))

Minor Speedometer operation impaired (7.8 (b) (i))

**MOT #12** 2019-09-23 09:33

**MOT test number** 999014958446

**Result** ✓ Passed

CarCheck.co.uk page 4/14



**MOT #11** 2019-09-23 09:32

MOT test number 142064365195

Result X Failed

Pass with rectification Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

Pass with rectification Offside Rear Registration plate lamp does not illuminate simultaneously with the

position lamps (4.7.2 (a))

(i))

Pass with rectification Nearside Rear Registration plate lamp does not illuminate simultaneously with

the position lamps (4.7.2 (a))

**MOT #10** 2019-09-14 12:59

MOT test number 503492802586

**Result** ✓ Passed

MOT #9 2019-03-14 12:14

**MOT test number** 792986977679

Result \( \sqrt{Passed} \)

Advice Rear Anti-roll bar linkage ball joint has slight play nearside/offside (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2019-03-13 15:11

**MOT test number** 286287651593

**Result** X Failed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)

MAJOR Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Anti-roll bar linkage ball joint has slight play nearside/offside (5.3.4 (a) (i))

MOT #7 2018-09-14 13:20

**MOT test number** 511971505105

CarCheck.co.uk page 5/14



**MOT #6** 2018-09-13 15:50

**MOT test number** 149636914070

**Result** X Failed

**DANGEROUS** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2018-03-13 13:36

**MOT test number** 341363416023

**Result** ✓ Passed

**Advice** Brake pad(s) wearing thin Near side & off side front (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2017-09-22 11:59

MOT test number 735297675977

Result 

Passed

**Advice** Both rear brake discs appear worn

**Advice** Nearside Front tyre has slight sidewall damage

**Advice** Both front brake discs slightly corroded on inner surface

CarCheck.co.uk page 6/14



MOT #3

MOT test number

146999280831

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)

MOT #2

MOT test number

Result

MOT #1

2016-10-07 12:53

338934574723

✓ Passed

MOT test number 640468754000

Result \( \sqrt{Passed} \)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	15 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 8/14



### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

o mier mistery	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***************************************	
********	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
Plate changes	More info >
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NIX.
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2012-09-28
Last registration	2024-03-07
Complete history	See info



Registration #1	2012-09-28	23 mi
Registration #2	2015-10-14	39.071 mi
Registration #3	2016-10-07	49.107 mi
Registration #4	2017-03-29	55.669 mi
Registration #5	2017-09-22	72.695 mi
Registration #6	2018-03-13	92.916 mi
Registration #7	2018-09-13	109.416 mi
Registration #8	2018-09-14	109.438 mi
Registration #9	2019-03-13	127.692 mi
Registration #10	2019-03-14	127.694 mi
Registration #11	2019-09-14	144.385 mi
Registration #12		11.117 es
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 es
Registration #16		11.117 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 13/14



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	87%
Pedestrian	41%
Safety systems	97%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1817 mm
Height	1426 mm
Length	4440 mm
Wheel base	2605 mm
Kerb weight	1690 kg
Max. allowed weight	2025 kg

# Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4 page 14	1/14

Number of axles 2

**Engine number** DYZE4035841