



PEUGEOT



PKI2TWC


report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 SPORTIUM
Colour	Black
Year of manufacture	2012
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-09
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2023-11-15
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	15
Total items failed	21

MOT #13 2023-12-05 16:09

MOT test number 681375683188

Result ✗ Failed

- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Central Rear Seat belt likely to become detached in the event of a collision UNBOLTED ? (7.1.1 (a) (ii))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Offside Headlamp insecure (4.1.1 (c))
- Fail** Body component damaged and likely to cause injury mirror cover (6.2.1 (a) (i))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Nearside Rear Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Exhaust rear heatshield loose

**MOT #12**

2022-11-15 13:59

**MOT test number**

889101109874

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 185/65/15 (5.2.3 (e))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MOT #11**

2022-11-08 10:34

**MOT test number**

727371069873

**Result**

✗ Failed

**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 185/65/15 (5.2.3 (e))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MOT #10**

2021-11-16 14:13

**MOT test number**

239807828326

**Result**

✓ Passed

**Advice** Front Brake disc worn, but not excessively Both side(NSF&OSF) (1.1.14 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing Both side(NSF&OSF) (5.2.3 (d) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))



<b>MOT #9</b>	2021-01-30 10:47
<b>MOT test number</b>	347899561851
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear exhaust bracket broken but still secure

<b>MOT #8</b>	2019-07-19 11:53
<b>MOT test number</b>	225796220577
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Rear exhaust hanger insecure

<b>MOT #7</b>	2018-07-06 13:23
<b>MOT test number</b>	853329499736
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

<b>MOT #6</b>	2018-07-06 13:23
<b>MOT test number</b>	381457608110
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
<b>Advice</b>	Offside Front Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
<b>Pass with rectification</b>	Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

<b>MOT #5</b>	2017-07-04 07:51
<b>MOT test number</b>	899018530933
<b>Result</b>	✓ Passed



<b>MOT #4</b>	2017-07-03 13:01
---------------	------------------

<b>MOT test number</b>	184305221378
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Front Windscreen washer provides insufficient washer liquid (8.2.3)
-------------	---

<b>MOT #3</b>	2016-05-04 15:39
---------------	------------------

<b>MOT test number</b>	778247695481
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2016-05-03 16:21
---------------	------------------

<b>MOT test number</b>	881623966197
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	---

<b>Fail</b>	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	--

<b>MOT #1</b>	2015-07-18 08:37
---------------	------------------

<b>MOT test number</b>	896299095153
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 October 2023

✕  
MOT

Expired:  
15 November 2023

Tax status	Expired at 31 October 2023
Days left	181 days too late
MOT expiry date	15 November 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-25
Last registration	2023-12-05
Complete history	<a href="#">See info</a>



Registration #1	2012-05-25	8 mi
Registration #2	2015-07-18	29.528 mi
Registration #3	2016-05-03	44.717 mi
Registration #4	2016-05-04	44.717 mi
Registration #5	2017-07-03	49.069 mi
Registration #6	2017-07-04	49.069 mi
Registration #7	2018-07-06	53.033 mi
Registration #8	2018-07-06	53.033 mi
Registration #9	2019-05-20	53.033 mi
Registration #10	2019-05-20	53.033 mi
Registration #11	2019-05-20	53.033 mi
Registration #12	2019-05-20	53.033 mi
Registration #13	2019-05-20	53.033 mi
Registration #14	2019-05-20	53.033 mi
Registration #15	2019-05-20	53.033 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1245 kg
Max. allowed weight	1617 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FSX46410607