





report date: 2024-03-28

General information

Make	BMW
Model	1 SERIES 116D EFFICIENTDYNAMICS
Colour	Black
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-01-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-05-26
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	12
Total items failed	2

MOT #13	2023-05-27 08:51
MOT test number	407216994970
Result	✓ Passed
Next expiry date	2024-05-26

MOT #12		2023-05-22 13:30
MOT test	number	984332503801
Result		X Failed
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
MAJOR (ii))	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ing	ress of dirt (5.3.4 (b)
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11	2022-05-26 15:34
MOT test number	984060853968
Result	✓ Passed

MOT #10	2021-10-23 09:08
MOT test number	136525365190
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #9 2020-11-04 14:07

MOT test number 132200259127

MOT #8 2020-10-26 10:17

MOT test number 442602348894

Result X Failed

MAJOR Front Position lamp not working Both fronts with ignition off (4.2.1 (a) (ii))

MOT #7 2020-03-24 10:32

MOT test number 702531716846

Result \rightarrow Passed

Advice Light switch loose

MOT #6 2019-03-21 17:58

MOT test number 608446744597

Result
✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Advice Nearside Rear Body panel slightly loose under door body panel damaged (6.2.1 (a) (i))

MOT #5 2019-03-21 15:27

MOT test number 236447289560

Result X Failed

MAJOR Nearside Front Position lamp not working (4.2.1 (a))

Advice Nearside Rear Body panel slightly loose under door body panel damaged (6.2.1 (a) (i))

MAJOR Offside Front Position lamp not working (4.2.1 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



MOT #4	2018-03-24 12:16
MOT test number	743353564088
Result	✓ Passed
MOT #3	2018-03-23 17:17
MOT test number	579737839891
Result	× Failed
Fail Front registration plate character(s) likely to be misread (6.3.4b)	
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	

MOT #2	2017-01-03 11:11
MOT test number	478262739387
Result	✓ Passed
MOT #1	2016-01-07 10:20
MOT test number	620005823439
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	26 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

•	
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
THE STATE OF THE S	

THE PARTY OF THE P	

	More info >
	Piore inio /
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK SILVE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-01-10
Last registration	2023-05-27
Complete history	See info



Registration #1	2013-01-10	11 mi
Registration #2	2016-01-07	21.376 mi
Registration #3	2017-01-03	27.509 mi
Registration #4	2018-03-23	39.303 mi
Registration #5	2018-03-24	39.376 mi
Registration #6	2019-03-21	48.370 mi
Registration #7	2019-03-21	48.370 mi
Registration #8	2020-03-24	52.847 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4324 mm
Wheel base	2690 mm
Kerb weight	1310 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles 2

Engine number 74698428