





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Silver
Year of manufacture	2010
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2024-10-31
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	20
Total items failed	7

MOT #16	2023-10-25 12:54
MOT test number	753580499907
Result	✓ Passed
Next expiry date	2024-10-31
Advice Shock absorbers has light misting of oil both rear (5.3.2 (b))	

MOT #15		2022-11-01 11:30
MOT test	number	738019275769
Result		✓ Passed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear Direction indicator slightly discoloured both (4.4.3 (a))	
Advice	Rear exhaust back box casing corroded	

MOT #14		2021-10-27 13:37
MOT test	number	698904255264
Result		✓ Passed
Advice	Both front anti roll drop link gaiters slightly damaged	
Advice	Offside front and nearside rear indicators slightly discoloured	

CarCheck.co.uk page 2/12



MOT #13

MOT test number

608761105208

Result

Advice Rear exhaust box corroded

MOT #12

MOT test number

937513629661

Result

MAJOR Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Rear exhaust box corroded

 MOT #11
 2019-10-28 10:47

 MOT test number
 148460225468

 Result
 ✓ Passed

MOT #10 2018-10-27 09:53

MOT test number 501895210238

Result ✓ Passed

 MOT #9
 2017-10-30 14:49

 MOT test number
 877357261994

 Result
 ✓ Passed

CarCheck.co.uk page 3/12



MOT #8 2017-02-02 09:35

MOT test number 872338021697

Result ✓ Passed

Advice Nearside door mirror casing damaged

Advice Nearside handbrake outer cable is broken

Advice Exhaust front pipe flexi is blowing slightly

MOT #7 2017-02-02 09:35

MOT test number 918520457588

Result X Failed

Advice Exhaust front pipe flexi is blowing slightly

Pass with rectification Offside Headlamp aim too high (1.8)

Pass with rectification Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)

Advice Nearside door mirror casing damaged

Advice Nearside handbrake outer cable is broken

Pass with rectification Nearside Headlamp aim too high (1.8)

Pass with rectification Offside Rear position lamp(s) adversely affected by the operation of another

lamp (1.1.A.3f)

MOT #6 2016-01-28 13:39

MOT test number 722255878534

Result ✓ Passed

MOT #5 2015-01-29 10:32

MOT test number 378399525016

Result

Passed

CarCheck.co.uk page 4/12



MOT #4 2015-01-29 10:32

MOT test number 526459325056

Result X Failed

Pass with rectification Front Headlamp not working on dipped beam (1.7.5a)

MOT #3 2014-02-05 10:56

MOT test number 148816834072

MOT #2 2013-02-04 10:15

MOT test number 158675933498

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2013-02-04 10:15

MOT test number 129685933493

Result X Failed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Headlamp aim too low (1.8)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Rear position lamp(s) incorrect colour (1.1.A.3e)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here .	
MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	AIR.
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-23
Last registration	2023-10-25
Complete history	See info



Registration #1	2010-03-23	8 mi
Registration #2	2013-02-04	30.387 mi
Registration #3	2014-02-05	40.047 mi
Registration #4	2015-01-29	49.041 mi
Registration #5	2016-01-28	56.967 mi
Registration #6	2017-02-02	65.383 mi
Registration #7	2017-02-02	65.383 mi
Registration #8	2017-10-30	68.358 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	★★★★ ★
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50
Fuel delivery	Multi-Point Injection
Number of doors	3
	70/70

CarCheck.co.uk page 12/12

Number of seats	4
Number of axles	2
Engine number	CHF 053362