



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 VIBE
Colour	Black
Year of manufacture	2008
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-03-16
Pictures	21
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-05
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	43
Total items failed	10

MOT #16	2023-11-24 13:03
MOT test number	278903693830
Result	✓ Passed
Next expiry date	2024-12-05

MOT #15	2022-12-06 14:40
MOT test number	526127556379
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	HORN HAS POOR SOUND
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2021-10-28 12:58
MOT test number	790658118142
Result	✓ Passed

**MOT #13**

2020-10-17 14:25

**MOT test number**

375277823930

**Result**

✓ Passed

**Minor**

Nearside Front Windscreen wiper blade defective rubber split (3.4 (b) (i))

**Advice**

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

**Advice**

Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner side very rusty (1.1.14 (a) (ii))

**Advice**

Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both rear chassis legs around spring hangers have surface rust (6.1.1 (c) (i))

**Advice**

Items removed from driver's view prior to test sat nav/phone holder ?

**Advice**

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner side very rusty (1.1.14 (a) (ii))

**Advice**

Oil leak, but not excessive lower engine area (8.4.1 (a) (i))

**MOT #12**

2019-05-02 14:16

**MOT test number**

358635070254

**Result**

✓ Passed

**Advice**

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Nearside rear tyre perished / cracking

**Advice**

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #11**

2018-04-07 13:08

**MOT test number**

334659136844

**Result**

✓ Passed

- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside rear bump stop missing
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside rear tyre perished / cracking
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Oil leak
- Advice** Windscreen wipers and washers poor
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10**

2017-04-10 16:55

**MOT test number**

438555133757

**Result**

✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside rear bump stop missing
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside windscreen wiper blade smeary

**MOT #9**

2017-04-10 12:53

**MOT test number**

505461239320

**Result****✗ Failed**

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside windscreen wiper blade smeary

**Fail** Offside Front wheel bearing rough when rotated (2.5.A.2)

**Advice** Offside rear bump stop missing

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Fail** Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Nearside Front Direction indicator incorrect colour (1.4.A.2f)

**Advice** Both rear tyres perished / cracking

**Advice** Offside Rear Nail in tyre

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8**

2016-03-30 11:16

**MOT test number**

609598753248

**Result****✓ Passed**

**Advice** All tyres over half worn

**MOT #7**

2015-04-02 12:13

**MOT test number**

669042895030

**Result****✓ Passed**

**Notice** O/s/f tyre over worn

**Notice** Damage to o/s/r wheel arch

**Notice** Rear exhaust hanger broken

**MOT #6** 2015-04-02 09:32**MOT test number** 297982295003**Result** ✗ Failed**Notice** Damage to o/s/r wheel arch**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Rear exhaust hanger broken**Notice** O/s/f tyre over worn**MOT #5** 2014-04-08 12:05**MOT test number** 296158194089**Result** ✓ Passed**MOT #4** 2013-04-10 15:49**MOT test number** 296880103463**Result** ✓ Passed**MOT #3** 2013-04-09 15:37**MOT test number** 136019393089**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #2** 2012-04-12 12:37**MOT test number** 269133602402**Result** ✓ Passed



MOT #1	2012-04-12 12:37
MOT test number	169143602152
Result	✗ Failed
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)





Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2024

✓

MOT

Expires:  
5 December 2024

Tax status	Expired at 1 April 2024
Days left	29 days too late
MOT expiry date	5 December 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-22
Last registration	2023-11-24
Complete history	<a href="#">See info</a>



Registration #1	2008-09-22	24 mi
Registration #2	2012-04-12	34.466 mi
Registration #3	2013-04-09	37.698 mi
Registration #4	2013-04-10	37.698 mi
Registration #5	2014-04-08	41.937 mi
Registration #6	2015-04-02	47.223 mi
Registration #7	2015-04-02	47.223 mi
Registration #8	2016-03-30	55.298 mi
Registration #9	2017-04-10	60.475 mi
Registration #10	2018-04-02	65.223 mi
Registration #11	2018-04-02	65.223 mi
Registration #12	2018-04-02	65.223 mi
Registration #13	2018-04-02	65.223 mi
Registration #14	2018-04-02	65.223 mi
Registration #15	2018-04-02	65.223 mi
Registration #16	2018-04-02	65.223 mi
Registration #17	2018-04-02	65.223 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	956 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W5074259